

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 03 Apr 2023

Preliminary Advice

Vehicle No	: SMK7611D	Accident Date	: 10/03/2023
Make	: HYUNDAI AD AVANTE	Policy No.	: SP2001652077
Assignment Date	: 14/03/2023	Excess	: S\$0.00
Date of Inspection	: 14/03/2023	Est. Duration of Repair	: 5
Inspection At	: SUCCESS UNITED PTE LTD (HQ) 2 KAKI BUKIT AVE 2 #01-33, KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,650.90
Revised Amount	:S\$	7,476.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,476.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	48,000.00
COE / PARF Rebate	:S\$	31,138.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,862.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Kindly approve repair cost \$7,476.80