

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305548235
Date 17.03.23

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH


Vehicle Reg No. SH 8725Y


Date of Accident : 10.03.23

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to : ALLIANZ --- SMK 76110
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c) Lumpsum Repair (If applicable)
Total for Lumpsum repair cost after Less: 20% \$4,100.00
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature : 
Name : TAUFIKH NAZ LKK
Date : 27/3/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	26.75/2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH8725Y

MAKE TOYOTA

MODEL PRIUS

DATE: 13.03.23

MVA JUMANI

DOA: 10.03.23

ALLIANZ

Qty*	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$503.04
1	REAR BUMPER CENTRE MLDG			\$654.96
1	REAR BUMPER BEAM			\$318.80
1	REAR FLOOR UNDER COVER			\$220.50
10	REAR BUMPER CLIPS			\$22.00
1	BOOTLID COVER			\$1,303.29
1	BOOTLID EMBLEM - PRIUS			\$62.14
1	BOOTLID EMBLEM - HYBRID			\$62.14
1	BOOTLID EMBLEM - STAR			\$81.43
1	REAR BUMPER TOW COVER			\$82.70
1	REAR WINDSCREEN GLASS MLDG			\$40.40
1	REAR FLOOR UNDER COVER			\$220.00
1	END PANEL			\$738.96
1	RELECTOR RH			\$55.00
1	BOOTLID COVER - OUTSIDE			\$1,054.71
	SUB TOTAL			\$5,420.07
	DIS 25%			\$1,438.50
	DISCOUNTED TOTAL			\$4,315.51
	BOOTLID COMFORT LOGO			\$30.00
	BOOTLID COMFORT TEL.NOS LOGO			\$30.00
	BOOTLID APPS LOGO			\$40.00
	REVERSE SENSOR			\$180.00
	SEALANT			\$46.00
				\$326.00
	Labour Charge			
	PANEL BEATING -			\$1,200.00
	SPRAY PAINT			\$900.00
	REMOVE/REFIX REVERSE SENSOR			\$50.00
	CHECK WIRING			\$50.00
	TUFF KOTE			\$50.00
	REMOVE/REFIX REAR WINDSCREEN GLASS			\$120.00
	ADVERTISEMENT LOGO - BUMPER			\$50.00
	TOTAL LABOUR			\$2,420.00
	ESTIMATE TOTAL			\$7,111.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL LABOUR

ESTIMATE TOTAL

Taught 97495749
 imp 14/3/23 C1300
 3 days
 L/S passing after repair
 taught C1300.com.

4240.61
 1060.15
 3180.46

1630

5136.46

1077.29

4109.17

C1300

ALLIANZ

dl

kl

bt

XSV

ney

bt

ner

ner

ne

his

ner

XSV

Ry

ent

ner

NET

NET

NET

NET

NET

NN

NN