BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D



= 6744 2377

Date: 14th Mar 2023, Tuesday

M/s China Taiping Insurance (S) Pte Ltd

C/O LKK Auto Consultants Pte Ltd

Dear Sir / Madam,

REF: Your Insured Vehicle SML5277T

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CASES (NIMA)

ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SNF9861A & SML5277T ON 12/03/2023

ALONG PIE TOWARDS TUAS AT 1405 Hrs.

Our client's vehicle – **SNF9861A** was damaged in the above accident.

A copy of the Singapore Accident Statement report filed is enclosed.

As a result of the accident, the vehicle has been damaged. We would like to appoint surveyor from your kind firm to conduct a pre-repair survey of the vehicle within 2 working days before we proceed to repair the damaged vehicle.

Please be informed that the said vehicle can be inspected at:

Name of Workshop: Best Solution Autocare Pte Ltd

Address: 53 Ubi Avenue 1 #03-01 Paya Ubi Industrial Park S(408934)

Contact Person: Ms CuiPing Telephone No: 6744 0777

Fax No: 6744 2377

Email Address: cuiping@carway.com.sg

Please note that if we do not receive any reply from you within the stipulated timeline, you will be deemed to have waived your rights to a pre-repair inspection. In view of that, we shall proceed to repair the vehicle without further reference to you.

Thank You

BEST SOLUTION AUTOCARE PTE LTD