

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

12 MARINA VIEW
#14-01 ASIA SQUARE TOWER 2
SINGAPORE 018961

TEL: 63958963

ATTN: Motor Claim Department \ ALLIANZ

Your Ref No: TP 0323-7304

Claim Type: Third Party

Accident Date: 03/03/2023

TP Veh Reg No: SMZ 9286 S

Estimate No: EST1509436

Date: 09 Mar 2023

Policy No: P10161161R03

Veh Reg No: SLR5386S

Make/Model: JAGUAR XF 2.0P TSS

Chassis No: SAJAC05M4EPU11148

Engine No: 130913124628204PT

Reg. Date: 29/04/2014

Estimate Repair Cost to Vehicle No :SLR5386S

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 FRONT BUMPER	3,321.600	1 PC	3,321.60	
2 FRONT BUMPER SIDE HOLDER - LH/RH	88.4000	2 PC	176.80	
3 FRONT BUMPER CLIPS	13.8000	10 PC	138.00	
4 FRONT BUMPER FOG LAMP COVER - LH/RH	342.5000	2 PC	685.00	
5 FRONT BUMPER FOG LAMP CHROME - LH/RH	575.8000	2 PC	1,151.60	
6 FRONT BUMPER CENTER LOWER GRILLE	341.6000	1 PC	341.60	
7 FRONT BUMPER FOAM	773.1000	1 PC	773.10	
8 FRONT BUMPER REINFORCEMENT	867.8000	1 PC	867.80	
9 FRONT BUMPER REINFORCEMENT UNDER TRAY	743.6000	1 PC	743.60	
10 FRONT BUMPER NUMBER PLATE GARNISH	261.2000	1 PC	261.20	
11 FRONT GRILLEWITH CHROME	2,163.300	1 PC	2,163.30	
12 FRONT GRILLE LOGO	178.4000	1 PC	178.40	
13 HEAD LAMP - RH	6,471.100	1 PC	6,471.10	
14 HEAD LAMP - LH	6,471.100	1 PC	6,471.10	
15 BONNET	5,733.700	1 PC	5,733.70	
16 FRONT BUMPER FOG LAMP CHROME - RH	575.8000	2 PC	1,151.60	
			30,629.50	
		Less 10%	3,062.95	27,566.55
Special Net				
17 FRONT NUMBER PLATE WITH CASING	45.0000	1 PC	45.00	
			45.00	45.00
Labour				
18 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	600.0000	1 JOB	600.00	
19 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	
20 TO CHECK WIRING	50.0000	1 JOB	50.00	
21 TO TUFF-KOTE	80.0000	1 JOB	80.00	
			1,530.00	1,530.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

12 MARINA VIEW

#14-01 ASIA SQUARE TOWER 2

SINGAPORE 018961

TEL: 63958963

ATTN: Motor Claim Department \ ALLIANZ

Your Ref No: TP 0323-7304

Claim Type: Third Party

Accident Date: 03/03/2023

TP Veh Reg No: SMZ 9286 S

Estimate No: EST1509436

Date: 09 Mar 2023

Policy No: P10161161R03

Veh Reg No: SLR5386S

Make/Model: JAGUAR XF 2.0P TSS

Chassis No: SAJAC05M4EPU11148

Engine No: 130913124628204PT


Reg. Date: 29/04/2014

Estimate Repair Cost to Vehicle No :SLR5386S

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 29,141.55
			Add GST @ 8%	2,331.32
			Total Amount Payable	<u>S\$ 31,472.87</u>

TOTAL: SINGAPORE DOLLAR THIRTY ONE THOUSAND FOUR HUNDRED SEVENTY TWO AND CENTS EIGHTY SEVEN ONLY

For Progressive Car Care Pte Ltd


AUTHORISED SIGNATURE