

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 15/03/2023

To : ALLIANZ INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 10/02/2023

Vehicle No : GBF-4981-L

Make & Model : NISSAN NV200 1.5 DIESEL G (M) EURO 5

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>Nett Item</u>			
1	FRONT BUMPER <i>see</i>	739.40	789.40
1	FRONT BUMPER RETAINER LH <i>XAN</i>	25.20	102
10	FRONT BUMPER CLIPS <i>see</i>	50.00	710.46
1	FRONT FENDER LH <i>see</i>		
	RESTORE		
	Sub Total	814.60	
	Discount 10% On Parts	(81.46)	
<u>Labour & Misc</u>			
	LABOUR TO FACILITATE REPAIR	300	400.00
	TO RESPRAY AFFECTED AREAS	200	400.00
			500

Date : 15/03/2023

To : ALLIANZ INSURANCE SINGAPORE PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 10/02/2023

Vehicle No : GBF-4981-L

Make & Model : NISSAN NV200 1.5 DIESEL G (M) EURO 5

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	800.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

710.46
500.00
1210.46
202
968.36
43-8950.00/200

Remarks:

Repair - Hp 900 10068
2 days 1L/S /A

1,533.14

SUB TOTAL

GST 8.0 % 122.65

TOTAL 1,655.79

Surveyor's name:

Ram

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 16/03/23 @ 1500