

Our Reference

: FA.9234.22.BL

Email

: accidentclaims@fazalllc.com.sg

admin@fazalllc.com.sg

Your Reference : C10007399

Date

: 21 June 2022

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

190 CLEMENCEAU AVENUE

#03-01

SINGAPORE 239924

Attn: Motor Claims Department

WITHOUT PREJUDICE

CERTIFICATE OF POSTING & EMAIL charandeep.s@budgetdirect.com.sg

Dear Sirs,

CLAIMANT – MOHAMED NOOR BIN MOHAMED HANIFA ACCIDENT ON 22.9.2020 ALONG TELOK BLANGAH ROAD INVOLVING MOTOR VEHICLES FBH800S & SDP9166P

We refer to the above matter.

We consolidated our client's claim as follows with supporting documents for your attention.

General Damages

•	Pain and Suffering	\$ 25,000.00
•	Loss of Earning Capacity	\$ 30,000.00
•	Future Medical expenses	\$ 15,000.00

Special Damages: -

(Medical and related expenses)

•	Medical Expenses	\$	2,410.72
•	Transportation	\$	40.00
•	Loss of income	to be a	assessed
•	Repair bills	\$	9,750.00
•	Loss of use (9 Days x \$20.00)	\$	180.00
•	Others	\$	1,678.00

..2/-

9 Jalan Kukoh #01-87 Singapore 160009 T: (65) 6535 2188 | F: (65) 6534 3972 [Not for Service of Court Documents] E: admin@fazalllc.com.sg



Disbursements incurred as to date:

		Total	\$ 86,632.66
•	Incidentals		\$ 150.00
•	Towing fees		\$ 250.00
•	Survey report fees		\$ 563.00
•	LTA search fees		\$ 7.49
•	Police report fees		\$ 30.00
•	GIA report fees		\$ 29.00
•	Medical report fees		\$ 1,544.45

plus Costs, GST and reasonable disbursements to be agreed or taxed.

We enclose herewith additional documents as follows for your attention and record:-

- Repair bill from LKT Group Pte Ltd;
- Survey report from United Appraisal and Management Pte Ltd dated 4 March 2022;
- Survey report photographs; and
- Survey report receipt from United Appraisal and Management Pte Ltd dated 4 March 2022;
- Invoice from HKL Lim Team Motorsport dates 20.12.2021, 24.12.2021 & 8.4.2022;
- Grab statement.

Our client reserves the right to vary the above stated quantification.

Please let us know whether you are prepared to settle our client's claim by making an offer of settlement (if any) as soon as possible.

We are open for a direct settlement, kindly call our Ms Nisha to negotiate settlement if any.

Please revert **URGENTLY** within the next 10 days.

Yours faithfully,

<u>enc</u>

9 Jalan Kukoh #01-87 Singapore 160009

T: (65) 6535 2188 | F: (65) 6534 3972 [Not for Service of Court Documents]

E: admin@fazalllc.com.sg




Proforma Invoice

To: Mohamed Noor Bin Mohamed Hanifa

Date

: 04 Mar 2022

DESCRIPTION	AN	MOUNT
Final repair bill	\$	9,750.00
Total	\$	9,750.00
Registration no. : FBH800S		
Make/Model : Kawasaki KR150K		
		:



Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singaore 415874
Handphone No.: +65 9146 1186 Email: united appraisal@live.com.sg
Business Registration Nos.: 200817301N

WITHOUT PREJUDICE

Our ref.: UAM21.07.32-AK-STP-LKT-FBH800S

Date : 04 Mar 2022

Motor Vehicle Appraiser

Encls.:

Mohamed Noor Bin Mohamed Hanifa

Dear Sir. Re: Third Party Claim For Vehicle Registration No. **FBH800S** We refer to your instruction to appraise the above-mentioned vehicle on 27 September 2021 A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. LKT Group Pte Ltd for SGD 13,703.36 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly. Our revised quotation for the repair is SGD 12,217.02. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced. We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle SGD 9,750.00 NETT. Which, in our opinion is fair and reasonable. The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs. Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 9 (Nine) We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisement schedule and invoice for services rendered. Please do not hesitate to contact us if you have any queries on this matter. Yours faithfully. United Appraisar & Management Pte Ltd Ananda K. Biswas Marc

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singaore 415874
Handphone No.: +65 9146 1186 Email: united.appraisal@live.com.sg
Business Registration Nos.: 200817301N

VEHICLE INSPECTION REPORT

To: Mohamed Noor Bin Mohamed Hanifa

Our ref.: UAM21.07.32-AK-STP-LKT-FBH800S

Date : 04 Mar 2022

REFERENCE

Assign by	:	Mohamed Noor Bin Mohamed Hanifa Insured			To be advice
Assign on	:	27 Sep 2021	Policy no.	:	To be advice
Inspection on	:	27 Sep 2021	Claim no.	:	To be advice
Accident on	:	22 Sep 2020	Sum insured	:	To be advice
Workshop name	:	LKT Group Pte Ltd	Excess	:	Not applicable
Inspection at	:	Blk 3006 Übi Rd 1	3rd party Veh.	:	To be advice
•		#01-384	3rd party ins.	:	To be advice

Singapore 408700

PARTICULARS OF DAMAGED VEHICLE

Registration no. : FBH800S Odometer : 32824 km

Make / Model : Kawasaki KR150K Chassis no. : KR150KA57234

Regn. date : 02 Sep 2003 Engine no. : KR150EEA57234

Body colour : Black Engine cap. : 148 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering : In order Paintwork : Good Footbrake : In order Undercarriage : Serviceable Handbrake : In order Gen. condition : Good

TYRE CONDITION ON VEHICLE

		Make	Size	Tread depth	Type of road wheel
Front N/S	;	Pirelli	90/80-17M	70%*	Alloy*
Front O/S	:	N/A	N/A	70%	N/A
Rear N/S	:	Pirelli	100/90-17M	70%*	Alloy*
Rear O/S	:	N/A	N/A	70%	N/A

NOTE: The above percentages represent the estimated remaining life of tyre threads.

^{*} Denotes damaged component/s

POINT OF IMPACT

On the front in the direction from right to left.

SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT

The impact of the collision has damaged / affected the front and rear wheel, front fender, front fork, handle bar, fuel tank, fairing, seat, gear pedal, rear brake pedal, footrest, headlight, taillight, chassis frame and etc...

Please refer to Annex A (Appraisement Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on xx abc 2021 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs

LKT Group Pte Ltd

as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 9,750.00 to carry out the repairs. Please refer to Annex A (Appraisement Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately 9 (Nine) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "WITHOUT PREJUDICE" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully, United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no. : FBH800S Our reference : UAM21.07.32-AK-STP-LKT-FBH800S

S/N	Otry	Description	Condition /	Estimate by	Adjusted
5/14	Qty	Description	Remarks	Wshop SGD	Amt SGD
		LIST ITEMS			
1	1	Front windshield	Missing	180.55	180.55
2	1	Front fairing	Missing	398.00	398.00
3	1	Front fairing inner cover	Missing	96.20	96.20
4	1	Front fairing inner bracket	Bend	179.88	179.88
5	2	Side fairing centre @ SGD 205.00	Missing	410.00	410.00
6	1	Side fairing lower @ SGD 196.00	Missing	392.00	392.00
7	1	Rear side fairing @ SGD 193.40	Grazed	386.80	386.80
8	1	Front fender	Cracked	98.12	98.12
9	lpair	Side mirror	Missing	90.00	90.00
10	1	Headlight	Missing	685.90	685.90
11	1	Headlight stay	Missing	220.00	220.00
12	1	Speedometer	Cracked	455.32	455.32
13	1	Speedometer cable	Snap	187.60	187.60
14	2	Front signal lamp @ SGD 38.00	Missing	76.00	76.00
15	2	Rear signal lamp @ SGD 38.00	Cracked	76.00	76.00
16	1	Handle bar	Bend	129.20	129.20
17	l set	Handle grip	Cut	67.56	67.56
18	1 set	Handle balancer	Grazed	48.00	48.00
19	1	Front brake master cylinder pump	Damaged	145.22	145.22
20	1	Front brake fluid reservoir	Damaged	136.89	136.89
21	1	Front brake lever	Bend	58.00	58.00
22	1	Front brake caliper	Jammed	287.00	287.00
23	1	Front rim shaft	Bend	28.15	28.15
24	1	Front wheel bearing	Necessary	28.15	28.15
25	1	Clutch lever	Bend	58.00	58.00
26	1	Clutch cable	Jammed	92.60	92.60
27	1	Steering spindle	Distorted	182.55	182.55
28	1	Steering stem	Distorted	190.75	190.75
29	2	Front fork inner tube @ SGD 220.00	Bend	440.00	440.00
30	2	Front fork outer tube @ SGD 140.00	Bend	280.00	280.00
18	1	Front fork top clamp	Distorted	169.00	169.00
32	1	Front fork under bracket	Distorted	148.30	148.30
33	2	Front footrest @ SGD 50.00	Snapped	00.001	100.00
34	2	Front footrest bracket @ SGD 90.00	Distorted	180.00	180.00
35	1	Gear pedal	Bend	145.00	145.00
36	1	Fuel tank	Dented	450.00	450.00
37	2	Air intake duct @ SGD 130.00	Cracked	260.00	260.00
38	2	Rear side board @ SGD 170.00	Cracked	340.00	
39	1	Rear swing arm	Distorted	420.00	
40	1	Rear rim shaft	Bend	34.50	
41	1	Rear wheel bearing	Necessary	35.00	
42	2	Rear footrest @ SGD 45.00	Snapped	90.00	
43	2	Rear footrest bracket @ SGD 120.00	Distorted	240.00	
44	1	Rear mudguard	Re-Used	85.00	0.00

APPRAISEMENT SCHEDULE

Annex A

Registration no. : FBH800S

Our reference

: UAM21.07.32-AK-STP-LKT-FBH800S


Taillamp	[a a .]			Condition		Adjusted
1 Rear seat assy	S/N	Qty	Description	Remarks	Wshop SGD	Amt SGD
1 Rear seat assy	45	1	Taillamn	Cracked	290.00	290.00
1 Radiator Cracked 236.42 236.42 236.42 236.42 18 Radiator fluid reservoir tank Missing 121.60 121.60 50.00					118.20	118.20
1 Radiator fluid reservoir tank Missing 121.60 121.60 121.60 121.60 121.60 50.00 5			•	Cracked	236.42	236.42
1 Radiator hose top				Missing	121.60	121.60
Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) Cut 25.00 25.00 55.90 55.90 55.90 55.90 65.90		-		-	50.00	50.00
1 Horn Refer To Labour 0.00 55.90 55.90 55.90 1.30			<u> </u>	Cut	25.00	25.00
Chassis frame				Malfunction	ı 55.90	55.90
Less 0%/10% 0.00 961.34				Refer To Labo	our 0.00	
SPECIAL NETT ITEMS SPECIAL NETT ITEMS		_			9698.36	9613.36
SPECIAL NETT ITEMS				Less 0%/10 ⁴		
1 1 Sundries Necessary 50.00 30.00 2 1 Body sticker Necessary 90.00 90.00 3 1 Fork oil Necessary 40.00 40.00 4 1 Fork oil seal Necessary 50.00 50.00 5 1 Front number plate Bend 70.00 50.00 6 1 IU unit Shorted 180.00 180.00 7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 1755.00 1695.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL Total Parts and Labour Cost of Repair 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02					9698.36	8652.02
1 Body sticker Necessary 90.00 90.00 3 1 Fork oil Necessary 40.00 40.00 40.00 40.00 40.00 50.00			SPECIAL NETT ITEMS			
1 Body sticker Necessary 90.00 90.00 3 1 Fork oil Necessary 40.00 40.00 40.00 40.00 50.00	1	1	Sundries	Necessary	50.00	30.00
1 Fork oil Necessary 40.00 40.00 40.00 40.00 40.00 40.00 50.00 50.00 50.00 50.00 50.00 60.00 60.00 60.00 60.00 60.00 7 1 IU unit Shorted 180.00 180.00 7 1 IU bracket Twisted 25.00 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 1755.00 1695.00 1755.00 1695.00 1755.00 1695.00 1755.00 1695.00 1755.00 1695.00 1755.00 1695.00 1755.00 1695.00 1755.00 1695.00 1755.00 1695.00 1755.00				Necessary	90.00	
1 Fork oil seal Necessary 50.00 50.00 5 1 Front number plate Bend 70.00 50.00 6 1 IU unit Shorted 180.00 180.00 7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 1755.00 1695.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02			•	Necessary	40.00	
5 1 Front number plate Bend 70.00 50.00 6 1 IU unit Shorted 180.00 180.00 7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL TOTAL 2250.00 1870.00 TOTAL			Fork oil seal	Necessary	50.00	
6 1 IU unit Shorted 180.00 180.00 7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 TOTAL 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02		1	Front number plate	Bend	70.00	
7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 TOTAL 2250.00 1870.00 TOTAL 2250.00 1870.00 TOTAL 2467.02				Shorted	180.00	
8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02		1	IU bracket	Twisted	25.00	
9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 1755.00 1695.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 TOTAL 2250.00 1870.00 TOTAL 2250.00 12217.02 Less (Lumpsum repair adjustment) 2467.02				Bend	780.00	780.00
10				Cracked	320.00	
11 1 Rear alloy rim R17 Wobbled 320.00 320.00 140.00 1755.00 1695.00 1755.00 1695.00 1755.00 1695.00 11453.36 10347.02		1	· · · · · · · · · · · · · · · · · · ·	Cut	150.00	
1 Rear tyre R17				Wobbled	320.00	320.00
TOTAL 1755.00 1695.00 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02			-	Abraided	160.00	
LABOUR & MISC CHARGES 350.00 320.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 1870.00 TOTAL 2250.00 1870.00 1870.00 Less (Lumpsum repair adjustment) 2467.02 2467.02 1870.00		_	•		1755.00	1695.00
1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02			TOTAL		11453.36	10347.02
To remove/replace damaged parts & components. To respray replaced & affected parts. TOTAL Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 700.00 650.00 2250.00 1870.00 13703.36 12217.02 2467.02			LABOUR & MISC CHARGES			
TOTAL 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02	1		To carry out body frame alignment		350.00	320.00
TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02 2467.02	2		To remove/replace damaged parts & componen	ts.	700.00	650.00
Total Parts and Labour Cost of Repair 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02	3		To respray replaced & affected parts.		1200.00	900.00
Less (Lumpsum repair adjustment) 2467.02			TOTAL		2250.00	1870.00
Less (Lumpsum repair adjustment) 2467.02						
Dess (Dumpsum repaix adjustment)			Total Parts and Labour Cost of Repair		13703.3	
Adjustment Parts and Labour Cost of Repair 9750.00						2467.02
			Adjustment Parts and Labour Cost of Re	epair		9750.00




























































Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singaore 415874
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

INVOICE

To: Mohamed Noor Bin Mohamed Hanifa

Date : 04 Mar 2022

c/o : LKT Group Pte Ltd

Blk 3006 Ubi Rd 1 Invoice No. : 8094123

#01-384

Singapore 408700

DESCRIPTION	AMOUNT
Service rendered for appraisal / inspection report :	
Professional inspection fees	SGD 563.00
Photographs 23 pcs	
Transport fees	
Re-inspection fees (work in progress, post repair inspection)	
Total	SGD 563.00
Singapore dollar : FIVE HUNDRED SIXTY THREE ONLY.	
Registration no. : FBH800S	
Make/Model : Kawasaki KR150K	
Our reference : UAM21.07.32-AK-STP-LKT-FBH800S	
ll payments made payee to:-	
' UNITED APPRAISAL & MANAGEMENT PTE LTD"	





HKL Lim Team Motorsport (53347346B)

1008 Bukit Merah Lane 3, #01-24, Alexandra Village Industrial Estate 159722 Singapore Singapore Tel No.: 62756566, 62756656 Fax No.: 62729291 Email: hkllimteam@gmail.com

(GST ID No.)

TAX INVOICE

INVOICE: INV-108406

Date :20/12/2021 (18:08:00)

Page : 1 of 1

Bill To Address

: MR.NOOR

Job Sheet No : INV21264

Vehicle No. : FBH800S Model

Mileage

PO No.

Payment : PAYNOW Client Code : C5856

88307389 Contact No.

Svs. Advisor Mechanic

Description	Qty	Unit Price Disc SGD	% Sub Total SGD	GST @ 7% SGD	Total Amount SGD
Labour Accident Repair Deposit PAYNOW ON 20/12/2021 \$400	1.00	400.00	400.00	0.00 0.00 0.00	400.00 0.00 0.00
Personia				0.00	0.00

Remarks

Next Service Due: 5,000 K or 20/03/2022, whichever comes first.

Goods sold are neither returnable nor refundable. Total Amt Due: 400.00 400.00 Thank you for your patronage and support. Rounding Adj.: 0.00 Hope to see you again on next service. Total: 400.00

Customer's Signature Name:

Authorised Signature



HKL Lim Team Motorsport (53347346B)

1008 Bukit Merah Lane 3, #01-24, Alexandra Village Industrial Estate 159722 Singapore Singapore

Tel No.: 62756566, 62756656 Fax No.: 62729291 Email: hkllimteam@gmail.com

(GST ID No.)

TAX INVOICE

INVOICE: INV-108421

:24/12/2021 (11:09:00) Date

: 1 of 1 Page

Bill To

: MR.NOOR

Job Sheet No : INV21279

Vehicle No. : FBH800S

Model Mileage

PO No.

: PAYNOW

Contact No. 88307389

Svs. Advisor Mechanic

Name:

Address

Payment Client Code : C5856

Description	Qty	Unit Price SGD	Disc %	Sub Total SGD	GST @ 7% SGD	Total Amount SGD
Parts		<u>56</u>				
Fork Oil seal + Dust Seal + Oil LH & RH	1.00 SET	130.00		130.00	0.00	130.00
Fork Inner Tube (Original)	2,00	130.00		260.00	0.00	260,00
Fork Inner Tube Shalf Bush	1.00	50.00		50.00	0.00	50.00
Center Under Cowling	1.00	60.00		60.00	0.00	60.00
Used Side Fairing LH & RH	2.00	60.00		120.00	0.00	120.00
Spray 3 Fairing	1.00	130.00		130.00	0.00	130.00
Brake Padel	1.00	80.00		80.00	0.00	80.00
Used Speedor Meter	1.00	120.00		120.00	0.00	120.00
Speedor Meter Gear	1.00	120.00		120.00	0.00	120.00
Speedor Cable	1.00	28.00		28.00	0.00	28.00
Liqui Moly 10W-40 RAGE 4T 1L	1.00 BTL	28.00		28.00	0.00	28.00
Spark plug	1.00	12.00		12.00	0.00	12.00
Head Light	1.00	220.00		220.00	0.00	220.00
Labour						
Towing	1.00	30.00		30.00	0.00	30.00
Deposit INV-108406	1.00	(400.00)		(400.00)	0.00	(400.00)
PAYNOW ON 23/02/2022 \$588, BALANCE \$400					0.00	0.00
Remarks						

Next Service Due: 5,000 K or 24/03/2022, whichever comes first

988.00 988.00 Goods sold are neither returnable nor refundable. Total Amt Due: Thank you for your patronage and support. Rounding Adj.: 0.00 Hope to see you again on next service. Total: 988.00 Customer's Signature Authorised Signature



HKL Lim Team Motorsport (53347346B)

1008 Bukit Merah Lane 3, #01-24, Alexandra Village Industrial Estate 159722 Singapore SIngapore Tel No.: 62756566, 62756656 Fax No.: 62729291 Email: hkllimteam@gmail.com

(GST ID No.)

TAX INVOICE

INVOICE: INV-109764

Date :08/04/2022 (19:16:00)

: 1 of 1 Page

Bill To Address

: MR.NOOR

Job Sheet No : INV23057

Vehicle No. : FBH800S Model

Mileage 0

PO No.

Payment : PAYNOW Client Code : C5856

Contact No. :88307389

Svs. Advisor Mechanic

Unit Price Disc % Sub Total GST @ 7% Total Amount Description Qty SGD SGD SGD SGD **Parts** BALANCE INV-108421 \$400 0.00 0.00 TOWING BACK CUSTOMER PLACE 1.00 35.00 35.00 0.00 35,00 STORAGE FEE 95.00 5.00 475.00 0.00 475.00 HEADLIGHT INV-108421 (220.00)0.00 (220.00)1.00 (220.00)

Remarks

Next Service Due: 5,000 K or 07/07/2022, whichever comes first.

Goods sold are neither returnable nor refundable. Total Amt Due: 290.00 Thank you for your patronage and support. Rounding Adj.: Hope to see you again on next service. Total:

Customer's Signature Name:

Authorised Signature

290.00

290.00

0.00

Annual Partner Statement



1 January, 2021 - 31 December, 2021

Paid to

Mohamed Noor Bin Mohamed Hanifa SG | POSB BANK *****3985 Summary

Total Earnings

Total Deductions

29,868.96

-42.09

Annual Net Earnings

S\$29,826.87

Earnings details

Cescripten:	žouoreá
Total Earnings	29,868.96
Deliveries Earnings	20,207 39
Incentives	7,756.55
Tips	563 44
Miscellaneous Earnings	1,341.58
Total Deductions	-42.09
Commission	-1 99
Adjustments	-40 10

Annual Net Earnings

S\$29,826.87

Weekly Breakdown

January 2021

√9 (±) + 1	Tsue-speart Luiterigs	ladistrains Etanorija	Bucklikgers	147.	Messellanssar. captilling	Constitution	Restal her c	Aledebrys	We∭gant∮resertati	Topid Larumys	Total Çega Adma	tDi€iaonegi
1-3 Jan	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
4 - 10 Jan	0,00	443.70	130.25	17.00	33,90	0.00	0.00	0.00	0.00	624.85	0.00	624,85
11 - 17 Jan	0.00	604.19	153.05	14.00	76.11	0.00	0.00	0.00	0.00	847.35	0.00	847.35

18 - 24 Jan	0.00	635.17	194.25	10.00	111.33	0.00	0.00	0.00	0.00	950,75	0.00	950.75
25 - 31 Jan	0.00	659.79	473.40	17.00	95.31	0.00	0.00	0.00	0.00	1,245.50	0.00	1,245.50
February 2021												
okanja)	*Elember of	Cindustrianida A tatkininista	fis in that.	16(1)	Monethysecon Country	Committee of the Commit	izgasi terce	Militale Service	Arlps desertes	Fisher Comments	Total	Neg vertangs
1 - 7 Feb	0.00	539.37	274.85	11.00	100.13	0.00	0.00	0.00	0.00	925.35	0.00	925.35
8 - 14 Feb	0.00	628.20	301,40	39.52	97.20	0.00	0.00	0.00	-40.10	1,066.32	-40.10	1,026.22
15 - 21 Feb	0.00	237.80	56.25	3,88	33,70	0.00	0.00	0.00	0.00	331.63	0.00	331.63
22 - 28 Feb	0.00	195.30	31.75	2.00	59.50	0.00	0.00	0.00	0.00	288.55	0,00	288.55
March 2021												
Stations	energy ser Edmindys	११४केल (काय हेनावसंस्था	fac esteget,	-45%	Messelfa a vers. Estestripo	Eurengrung schleib	Francisco (aux	Wetrije (166)	Adjut lasseds	agal tastico§.	iotal Certarteas	Петвыненну.
1 - 7 Mar	0.00	406.50	18.00	13.00	123,70	0.00	0.00	0.00	0.00	561.20	0.00	561.20
8 - 14 Mar	0.00	493,40	325.75	16.00	122.40	0.00	0.00	0.00	0.00	957.55	0.00	957.55
15 - 21 Mar	0.00	300.10	87.50	12.00	65.50	0.00	0.00	0.00	0.00	465.10	0.00	465.10
22 - 28 Mar	0.00	413.40	115.50	20.00	66.20	0.00	0.00	0.00	0.00	615.10	0.00	615.10
29 Mar - 4 Apr	0.00	424.70	146,50	3.00	95.70	0.00	0.00	0.00	0.00	669.90	0.00	669,90
April 2021												
Telegal	Гозапірія Істануу	Code Actions, Electricists	to estima,	iη·.	lstephilla recep. Indomés	Çerriz eser	Pental Lye	detejo (165.	Adjust neons	(Grafi Larre V)	loud Gestart sevs	feet commission
5 - 11 Apr	0.00	503.50	239.00	34.00	122.60	0.00	0.00	0.00	0.00	899,10	0.00	899.10
12 - 18 Apr	0.00	286.80	119.25	9.00	34.60	0.00	0.00	0.00	0.00	449,65	0.00	449,65
19 - 25 Apr	0.00	256.10	44.00	8.00	29.30	0.00	0.00	0.00	0.00	337.40	0.00	337.40
26 Apr - 2 May	0.00	299.50	52.50	12.00	57.90	0.00	0.00	0.00	0.00	421.90	0.00	421.90
May 2021												
Poggaj	nergyper Lengther	indeplas Labelys	Incostigues	$\epsilon_{\rm L}$:	Majurilly a esta Carrenty,	Country william	le-chg (v -	yernik (100, t	andgajadnis narata	ikāul Kaitursja	festal Special texas	thet southerests
3 - 9 May	0.00	524,70	125.00	8.00	0.00	0.00	0.00	0.00	0.00	657.70	0.00	657,70
10 - 16 May	0.00	260.50	80.50	2.00	0.00	0.00	0.00	0.00	0.00	343.00	0.00	343.00

17 - 23 May	0.00	524.40	87.50	15.00	0.00	0.00	0.00	0.00	0.00	626.90	0.00	626.90
24 - 30 May	0.00	107.50	46.25	1.00	0.00	0.00	0.00	0.00	0.00	154.75	0.00	154.75
31 May - 6 Jun	0.00	74.90	2.00	0.00	0.00	0.00	0.00	0.00	0.00	76.90	0.00	76.90
June 2021												
- Harris de la companya de la compa	Tenengy ve Entantely	Coductions Continues	las er fræds	Fig. 1	Modellisense.	Elekty Sangarant	Redd best	(sapalahan)	Andreas description	Varat Carro Sp.	čipad Seriqi turvo	Goldenburgs
7 - 13 Jun	0.00	259.57	7.50	10.00	0.00	-1.99	0,00	0.00	0.00	277.07	-1.99	275.08
14 - 20 Jun	0.00	357.50	76.25	6.00	0.00	0.00	0.00	0.00	0.00	439,75	0.00	439.75
21 - 27 Jun	0.00	265.40	32.50	3.00	3.00	0.00	0.00	0.00	0.00	303.90	0.00	303,90
28 Jun - 4 Jul	0.00	432.10	121,50	23.00	3.00	0.00	0.00	0.00	0.00	579.60	0.00	579.60
July 2021												
destod	nakyat basatn	ledez och beradzs	स्था स्था <u>स्था</u> ण	± 25°	Mexithenion Ennityt	Europey (granter)	foestal (see	detallet en	Adjust to a west s	ograf Eastweig	insal Omlastans	Насканалер;
5 - 11 Jul	0.00	597,70	210.40	17.00	0.00	0.00	0.00	0.00	0.00	825.10	0.00	825.10
12 - 18 Jul	0.00	498.50	146.80	12.00	0.00	0.00	0.00	0.00	0.00	657.30	0.00	657.30
19 - 25 Jul	0,00	686,10	279.00	26.00	0.00	0.00	0.00	0.00	0.00	991.10	0.00	991.10
26 Jul - 1 Aug	0.00	306.50	57.00	2.00	0.00	0.00	0.00	0.00	0.00	365.50	0.00	365.50
August 2021												
Perend	for Sport Executory,	Ondergraphy Entrophys	Batter-History	E _{eg} +.	Minnellinestor, Franciscips	(particular)	Gestal Ceer	Betalik i kors	Adam Crastile	famesj.	lidal Gedia terra	Gerganney,
2 - 8 Aug	0.00	408.50	106.00	12.00	3.00	0.00	0.00	0.00	0.00	529.50	0.00	529.50
9 - 15 Aug	0.00	270.70	60.50	12.24	0.00	0.00	0.00	0.00	0.00	343.44	0.00	343,44
16 - 22 Aug	0.00	523.30	246.15	3.12	0.00	0.00	0.00	0.00	0.00	772.57	0.00	772.57
23 - 29 Aug	0.00	698.00	304.20	24.68	0.00	0.00	0.00	0.00	0.00	1,026.88	0.00	1,026.88
30 Aug - 5 Sep	0.00	329.80	96.25	9.00	0.00	0.00	0.00	0.00	0,00	435.05	0.00	435.05
September 2021												
Prompt	sundjunts Equisionis	विकास स्थान स् स्थान स्थान स्	In costicos,	-1,1	Langelline envi Langelline	Paraktisa diapat	io o dal Cam	Vehajk Fee .	Adjosta esta	1 cg 2 g 2 g 2 g 2 g 2 g 2 g 2 g 2 g 2 g	inial ()criyetynes	blet suffice pt
6 - 12 Sep	0.00	626.10	335.15	14.00	0.00	0.00	0.00	0.00	0.00	975.25	0.00	975.25

13 - 19 Sep	0.00	33.20	51.00	0.00	0.00	0.00	0.00	0.00	0.00	84.20	0.00	84.20
20 - 26 Sep	0.00	846.80	207.05	24.00	0.00	0.00	0.00	0.00	0.00	1,077.85	0.00	1,077.85
27 Sep - 3 Oct	0.00	288.50	224.75	10.00	0.00	0.00	0.00	0.00	0.00	523.25	0.00	523.25
October 2021												
ercrassi	Okaragalat Elprotegy	fielderfield Fischerp	lio sertizari,	18 ₁ 0.	Macella vicus Carrenge	Carrier years	Rappid from	Vigina ke feser (And the second second second	ិសស្រី សមានរដ្ឋា	Noted Device to pro-	faktikskharjs
4 - 10 Oct	0.00	232.50	31.65	11.00	0.00	0.00	0.00	0.00	0.00	275.15	0.00	275.15
11 - 17 Oct	0.00	0.00	14.00	0.00	0.00	0.00	0.00	0.00	0.00	14.00	0.00	14.00
18 - 24 Oct	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
25 - 31 Oct	0.00	333.80	76.25	11.00	2.50	0.00	0.00	0.00	0.00	423.55	0.00	423.55
November 2021												
Progress	Compat Compat	i Sukurrisani Kasaaraya	for estimen	\$q\$	Merce Na se sar Encanço	Committees was	id-tylkali (entr.	rwette lik filen (Adagra (work),	l celu l Exercises	inski Distributionsk	lipo padanisty:
ਜ਼ਮਨਤ 1 - 7 Nov			to assume.	19.00	Meso Na se sio Escango 5.00	Consults van	inapped from	ownelie Feet 1	Salppa (sent)		Total Defections 0.00	тра <i>ва</i> льяря 626.40
	Emmys	Elsterry								\$2000g		
1 - 7 Nov	0.00	402.40	200.00	19.00	5.00	0.00	0.00	0.00	0.00	626.40	0.00	626.40
1 - 7 Nov 8 - 14 Nov	0.00 0.00	402.40 682.90	200.00 521.95	19.00 14.00	5,00	0.00	0.00	0.00	0.00	626.40	0.00	626.40 1,218.85
1 - 7 Nov 8 - 14 Nov 15 - 21 Nov	0.00 0.00 0.00	402.40 682.90 274.00	200.00 521.95 143.00	19.00 14.00 3.00	5.00 0.00 0.00	0.00 0.00 0.00	0.00	0.00	0.00 0.00 0.00	626.40 1,218.85 420.00	0.00	626.40 1,218.85 420.00
1 - 7 Nov 8 - 14 Nov 15 - 21 Nov 22 - 28 Nov	0.00 0.00 0.00 0.00	402.40 682.90 274.00 245.80	200.00 521.95 143.00 79.50	19.00 14.00 3.00 5.00	5.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00	626.40 1,218.85 420.00 330.30	0.00 0.00 0.00 0.00	626.40 1,218.85 420.00 330.30
1 - 7 Nov 8 - 14 Nov 15 - 21 Nov 22 - 28 Nov 29 Nov - 5 Dec	0.00 0.00 0.00 0.00	402.40 682.90 274.00 245.80	200.00 521.95 143.00 79.50	19.00 14.00 3.00 5.00 0.00	5.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	626.40 1,218.85 420.00 330.30 523.10	0.00 0.00 0.00 0.00	626.40 1,218.85 420.00 330.30 523.10
1 - 7 Nov 8 - 14 Nov 15 - 21 Nov 22 - 28 Nov 29 Nov - 5 Dec December 2021	0.00 0.00 0.00 0.00 0.00	402.40 682.90 274.00 245.80 344.60	200.00 521.95 143.00 79.50 178.50	19.00 14.00 3.00 5.00 0.00	5.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	626.40 1,218.85 420.00 330.30 523.10	0.00 0.00 0.00 0.00	626.40 1,218.85 420.00 330.30 523.10
1 - 7 Nov 8 - 14 Nov 15 - 21 Nov 22 - 28 Nov 29 Nov - 5 Dec December 2021	0.00 0.00 0.00 0.00 0.00	402.40 682.90 274.00 245.80 344.60	200.00 521.95 143.00 79.50 178.50	19.00 14.00 3.00 5.00 0.00	5.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	626.40 1,218.85 420.00 330.30 523.10	0.00 0.00 0.00 0.00 fixed	626.40 1,218.85 420.00 330.30 523.10

How to read this statement

0.00

0.00

230.30

630.60

70.10

433.00

20 - 26 Dec

27 - 31 Dec

Transport Earnings Total fares earned including other earnings related to the bookings (ei, surcharge, cancellation compensation)

0.00

0.00

1.00

16.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

301,40

1,079.60

0.00

0.00

301,40

1,079.60

Deliveries EarningsTotal earnings from Grabfood, GrabMart and Grab Express earnings

Incentives Total eligible incentives for both transport and deliveries

Tips Total tips earned for both transport and deliveries

Miscellaneous

Earnings

Total topup for miscellaneous items

Commissions Total commissions deducted for Transport and Deliveries bookings (if applicable)

Rental Fees Total deductions for all rental expenses recorded in driver's wallet

Vehicle Fees Total deductions for all vehicle expenses such as insurance recorded in driver's wallet

Adjustments Total deductions for miscellaneous items

Due to rounding, numbers presented throughout this document may not add up precisely to the totals provided.

The information shared with you is highly confidential and is only to be used for the performance of your Service. Any disclosure without the company's written consent shall be deemed as a breach of the Conditions of Use of the App and will affect your continued use of the same.