

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

*CS/MSG23002818/4*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SNG 3134*  
at Workshop m/s *7hm 10am*

of \_\_\_\_\_

Insured: *X299425*

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: *068k*

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *704J*

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *SNG 3134* Yr Regn: *26/92/10*

Type: *M. Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(A)*

Make: *BMW 520i* c.c. *1995*

Colour: *Blue* A/C: Insured / Std / NI / NA

Sp. Reading: *168636* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *WBANT12000CX30440*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *Order* / Jammed / Leaked / Burnt or

Brake: *Order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *225/55-216*

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *FALKEN*

Front: *6* Rear: *6*

R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *15/03/23* D.O.I. *21/03/23*

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*N/S Body*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *25-02-2030 AM 10K.*

*See note 25-02-2030 AM 26377*

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_\_ S + RS \_\_\_\_\_ SI

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	704J
Vehicle Details	
Vehicle No.:	SNG313U
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2023
Vehicle Make:	B.M.W.
Vehicle Model:	520i AUTO ABS AIRBAG 2WD XENON HEADLAMP
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	A569I522N46B20BE
Chassis No.:	WBANT12000CX30440
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$42,909.00
Original Registration Date:	26 Feb 2010
First Registration Date:	26 Feb 2010
Transfer Count:	2
Actual ARF Paid:	\$42,909.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Feb 2030
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$38,071.00
COE Rebate Amount:	\$26,377.00
Total Rebate Amount:	\$26,377.00

The information contained herein is correct as at 21 Mar 2023

OK



New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

2012 Mercedes C180 Coupe.



Super Low Ownership, Well  
Maintained By Female Owner  
**Direct Owner** StarAd

Sort by  20 results/page

1 vehicles



BMW 520 2030

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>BMW 520 2030</b>		Any	Any	> 10 year(s) old	Any	Any	Any	<b>Available</b>
	<b>BMW 5 Series 520i XL (COE till 01/2030)</b>		<b>\$75,800</b>	\$11,030 /yr	08-Feb-2010	1,995 cc	122,000 km	Luxury	<b>Available</b>
This 2 owner 5 series still in the top condition. Low usage and still new condition ESP the interior, the leather like a new car, no crack nor tear. Rd tax is new, 4 Michelin tyres still new, just serviced few days ago, no repair needed. STA/Vicom inspection welcome! Well maintal...									
Posted: 01-Mar-2023									

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view **Expired ads**

20 results/page

**Buy / Rent Cars**

New Cars For Sale

Used Cars For Sale

Cars For Rent

**Sell Your Car**

Post an Ad

Sell by Bidding

Sell by Consignment

**Aftermarket**

Workshop Directory

Aftermarket Products

**Articles**

Car Reviews

Car Advice

Car News

Car Features

**General**

About Us

Contact Us

Careers

Site Map

**Resources**

COE Prices

Car Loan Calculators

Car Forum

Car Insurance

Car Valuation

COE Renewal

Used Car Warranty

Bidded Carplates

Carpark Rates

**Follow Sgcarmart.com**

Sgcarmart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used BMW 520 2030, BMW 520 2030 Singapore, used BMW 520 2030 Singapore, used BMW 520 2030, used vehicles Singapore or even buy used BMW 520 2030 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on Sgcarmart.com are gathered from sources and based on algorithms that are believed by Sgcarmart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. Sgcarmart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Terms of Service Privacy Policy Personal Data Protection Statement ©2004-2023 Sgcarmart, Singapore. All rights reserved.

Compare



**TLM Automobile Pte Ltd****1 Defu Lane 6 Singapore 539365****UEN number: 202244624K**

Ms Choo Cher Peng Catherine

Estimate To Repair

SNG313U - BMW 520i

Chassis No : WBANT12000CX30440

Third Party Insurer: MSIG Insurance

Date of accident : 15 Mar 2023

Date: 18 Mar 2023

not Authorized  
her

21/3/23

L/SB

4 days

take the after repair

S/No	Quantity	Description	Amount
<b>LIST ITEMS</b>			
1	1 pc	Side mirror assy LH <i>SVC</i>	\$ 685.00
2	1 pc	Side mirror cover LH <i>CUT</i>	\$ 190.00
3	1 pc	Front door LH <i>301400</i>	\$ 2,460.00
4	1 pc	Front door outer handle LH <i>CUT</i>	\$ 195.00
5	1 pc	Front door black sticker LH <i>new</i>	\$ 105.00
6	1 pc	Front door glass outer moulding LH <i>new</i>	\$ 225.00
7	1 pc	Front door glass run channel LH <i>11</i>	\$ 270.00
8	1 pc	Front door inner lock LH <i>11</i>	\$ 620.00
9	1 pc	Front door glass regulator LH <i>11</i>	\$ 495.00
10	1 pc	Front door glass regulator motor LH <i>11</i>	\$ 420.00
11	1 pc	Front door glass guide LH <i>11</i>	\$ 150.00
12	1 pc	Front door frame moulding LH <i>11</i>	\$ 240.00
13	1 pc	Front door insulation LH <i>11</i>	\$ 150.00
14	1 pc	Front door inner trim board LH <i>11</i>	\$ 895.00
15	1 pc	Front door inner trim board clips <i>11</i>	\$ 35.00
16	1 pc	Front door weatherstrip LH <i>new</i>	\$ 250.00
17	1 pc	Rear door LH <i>11</i>	\$ 2,450.00
18	1 pc	Rear door black sticker LH <i>new</i>	\$ 105.00
19	1 pc	Rear door lower hinge LH <i>11</i>	\$ 185.00
20	1 pc	Rear door glass regulator LH <i>11</i>	\$ 480.00
21	1 pc	Rear door glass regulator motor LH <i>11</i>	\$ 450.00
22	1 pc	Rear door weatherstrip LH <i>new</i>	\$ 255.00
23	1 pc	Side skirt garnish LH <i>11</i>	\$ 680.00
24	1 set	Side skirt garnish clips <i>11</i>	\$ 35.00
			\$ 12,025.00
Less 5%			\$ 601.25
			\$ 11,423.75

**TLM Automobile Pte Ltd**  
**1 Defu Lane 6 Singapore 539365**  
**UEN number: 202244624K**

Ms Choo Cher Peng Catherine

Third Party Insurer: MSIG Insurance

Date of accident : 15 Mar 2023

Date: 18 Mar 2023

Estimate To Repair

SNG313U - BMW 520i

Chassis No : WBANT12000CX30440

S/No	Quantity	Description	Amount
		b/f :	\$ 11,423.75
		<b><u>LABOUR &amp; MISC. CHARGES</u></b>	
1		To check electrical lighting concerned.	\$ 100.00
2		To transfer of both front doors and o/s rear door fittings and perform water seepage test. @ \$120.00	\$ 240.00
3		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 200.00
4		Using onboard scan tool (OBD) perform full engine diagnostic check, to configure and clear, reset SRS service light.	\$ 200.00
5		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,200.00
6		Putty and spray painting of the affected portion.	\$ 1,400.00
7		To rust proof affected areas.	\$ 300.00
			\$ 3,640.00
		<b>Grand Total</b>	<b>\$ 15,063.75</b>

20  
120  
X  
X  
400  
600  
60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: