

(08/15/13) wsf

ASS. REC. BY: 7/1/13

REF:

CS/AIS23002845/Rvg3

459H

106-2025/Am

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

SKX 2585

Yr Regn:

2015 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKX 2585

at Workshop m/s

MOVA

of

BUKIT MERAH

Insured:

AIS

Policy No.

Claims No.

Sum Insured:


Excess:

1100

(Client's Record)

Make of Veh:

(Policy Condition)

Remark The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

SSK

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

15/03/23

D.O.I.

20/03/23

Survey held at

MOVA (BN)

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 22K

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) S + RS SI

) Photos

) Others



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 169722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: Allianz Insurance Singapore Pte, Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2004587879	Date of Loss:	15/03/2023
Vehicle Reg. No.:	SKX258S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIAO BANG XIONG		

Make/Model:	BMW 318i, 1.5 SEDAN LED NAV (A)	Vehicle Reg. Date:	17/08/2015
Vehicle Colour:	SILVER	Chassis No:	WBA8E32070K497522
Engine No:	F2361184B38B15A		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	19,422.70
Labour	45.00
Paintwork Labour	2,640.00
Towing	0.00
	0.00
Gross Total (\$\$)	22,107.70
+ GST 8.00% (\$\$)	1,768.62
Nett Amount (\$\$)	23,876.32

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

PAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Mar 2023)
 Parts: 143 BMW 318I 1.5 SEDAN LED NAV (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKX258S)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET <i>bt</i>			
2	2		*BONNET HINGE L+R <i>X</i>	0.00	0.00	*1,500.00 F
3	2		*BONNET LOCK LOWER L+R <i>?</i>	0.00	0.00	*270.00 F
4	2		*BONNET LOCK TOP L+R <i>?</i>	0.00	0.00	*240.00 F
5	2		*BONNET LOCK TOP COVER L+R <i>?</i>	0.00	0.00	*90.00 F
6	1		*BONNET RUBBER <i>an</i>	0.00	0.00	*30.00 F
7	1		*FRONT LOGO <i>an</i>	0.00	0.00	*90.00 F
8	2		*FRONT GRILLE L+R <i>can</i>	0.00	0.00	*110.00 F
9	2		*HEADLAMP L+R <i>can</i>	0.00	0.00	*250.00 F
10	2		*HEADLAMP BRACKET L+R <i>?</i>	0.00	0.00	*5,200.00 F
11	2		*HEADLAMP PANEL L+R <i>requir</i>	0.00	0.00	*56.00 F
12	2		*HEADLAMP CLIPS <i>an</i>	0.00	0.00	*400.00 F
13	1		*SUPPORT TOP PANEL <i>bt</i>	0.00	0.00	*24.00 F
14	1		*SUPPORT AIR DUCT TOP <i>?</i>	0.00	0.00	*275.00 F
15	1		*SUPPORT AIR DUCT LOWER <i>?</i>	0.00	0.00	*255.00 F
16	1		*SUPPORT V BAR <i>?</i>	0.00	0.00	*210.00 F
17	1		*FRONT FENDER RH <i>bt</i>	0.00	0.00	*150.00 F
18	1		*FRONT FENDER COWLING RH <i>de</i>	0.00	0.00	*770.00 F
19	10		*FRONT FENDER COWLING RIVET <i>one</i>	0.00	0.00	*210.00 F
20	1		*FRONT FENDER BRACKET RH	0.00	0.00	*30.00 F
21	1		*FRONT BUMPER <i>form</i>	0.00	0.00	*58.00 F
22	1		*FRONT BUMPER TOW COVER RH <i>mis</i>	0.00	0.00	*2,100.00 F
23	1		*FRONT BUMPER LOWER GRILLE <i>X</i>	0.00	0.00	*69.00 F
24	1		*FRONT BUMPER WASHER COVER RH <i>mis</i>	0.00	0.00	*180.00 F
25	1		*FRONT BUMPER WASHER JET <i>?</i>	0.00	0.00	*70.00 F
26	1		*FRONT BUMPER SPONGE <i>X</i>	0.00	0.00	*155.00 F
27	1		*FRONT BUMPER REINFORCEMENT <i>bt</i>	0.00	0.00	*90.00 F
28	2		*FRONT BUMPER REINFORCEMENT BRACKET L+R <i>X</i>	0.00	0.00	*490.00 F
29	2		*FRONT BUMPER BRACKET L+R <i>an</i>	0.00	0.00	*280.00 F
30	2		*FRONT BUMPER RETAINER L+R <i>m</i>	0.00	0.00	*70.00 F
31	10		*FRONT BUMPER RIVET <i>an</i>	0.00	0.00	*60.00 F
32	1		*A/C CONDENSER <i>?</i>	0.00	0.00	*30.00 F
33	1		*RADIATOR <i>?</i>	0.00	0.00	*1,270.00 F
34	1		*RADIATOR TOP HOSE <i>X</i>	0.00	0.00	*980.00 F
35	1		*RADIATOR BY PASS HOSE <i>X</i>	0.00	0.00	*210.00 F
36	2		*RADIATOR SIDE BRACKET L+R <i>X</i>	0.00	0.00	*115.00 F
37	2		*RADIATOR TOP MOUNTING L+R <i>X</i>	0.00	0.00	*200.00 F
38	2		*RADIATOR TOP BRACKET L+R <i>X</i>	0.00	0.00	*40.00 F
39	1		*RADIATOR LOWER HOSE <i>X</i>	0.00	0.00	*50.00 F
40	1		*AIR CLEANER BOX ASSY <i>can</i>	0.00	0.00	*180.00 F
41	1		*AIR DUCT <i>?</i>	0.00	0.00	*680.00 F
42	1		*AIR HOSE <i>X</i>	0.00	0.00	*55.00 F
				0.00	0.00	*65.00 F

F=Franchise part.

Sub Total (\$\$)	17,657.00
+ Margin on L,N Items 10.00% (\$\$)	1,765.70
Total Parts (\$\$)	19,422.70

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty Particulars

Miscellaneous Items

Amount

1 FRONT NUMBER PLATE *CA*35 ~~48.00~~

Sub Total (S\$)

45.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TOWING CHARGES - TO BE CONFIRM		
2	TO CUT & WELD SUPPORT PANEL, TO REPAIR FRONT FENDER L+R, FRONT CHASSISMEMBER FRONT DOOR L+R, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS	New	700
3	TO SPRAY AFFECTED AREAS, FRONT DOOR L+R, FRONT FENDER L+R, BONNET, SUPPORT PANEL, FRONT BUMPER & AFFECTED AREAS	New	1,000.00
4	TO REMOVE & REFIX A/C CONDENSOR, ELECTRIC FAN, HOSE, PIPE, VACUUM & REFILLING GAS	New	700
5	TO REMOVE & REFIX AIR CLEANER BOX, RADIATOR & OTHER ATTACHMENT PARTS	New	100?
6	TO DIAGNOSTIC & PROGRAMMING WERE NECESSARY	New	150

Gross Labour Cost (S\$)

2,640.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Rahul**Hq 90010068**8 days**4/8**26/03/23 @ 1650**EXCESS: 1100**Revert**Resy after repair*

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 459H

Vehicle Details

Vehicle No.: SKX258S
Vehicle to be Exported: No
Intended Deregistration Date: 20 Mar 2023
Vehicle Make: B.M.W.
Vehicle Model: 318I SEDAN LED NAV
Primary Colour: Silver
Manufacturing Year: 2015
Engine No.: F2361184B38B15A
Chassis No.: WBA8E32070K497522
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$29,417.00
Original Registration Date: 17 Aug 2015
First Registration Date: 17 Aug 2015
Transfer Count: 6
Actual ARF Paid: \$28,184.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Aug 2025
PARF Rebate Amount: \$16,910.00

Intended COE Rebate Details

COE Expiry Date: 16 Aug 2025
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$69,001.00
COE Rebate Amount: \$15,758.00
Total Rebate Amount: \$32,668.00

BMW 3 Series 318i

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[M](#)**Price****\$55,800****Depreciation** ⓘ

\$17,240 /yr

[View models with similar depre](#)**Reg Date**

31-Aug-2015

(2yrs 5mths 10days COE left)

Mileage

N.A.

Manufactured ⓘ

2015

Road Tax ⓘ

\$684 /yr

Transmission

Auto

Dereg Value ⓘ\$30,468 as of today ([change](#))**OMV** ⓘ

\$28,677

COE ⓘ

\$57,885

ARF ⓘ

\$27,148

Engine Cap

1,499 cc

Power

100.0 kW (134 bhp)

Curb Weight ⓘ

1,425 kg

No. of Owners ⓘ

5

Type of Vehicle

Luxury Sedan