

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/03/2023

User ID : munsan

Section A - Accident Details

Registration Number	SHC4915Z
Case Reference Number	TAX/03/23/2042
Registration Date	19/2/16
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YEW LENG WHATT
Type of Accident	Head To Side
Accident Date and Time	19/3/23 2:40 PM
Accident Reported Date and Time	20/3/23 9:25 AM
Is Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117933
Special Instruction to ARC, if any	DAMAGE - RH REAR TP FAULT CODE
Prepared Date and Time	20/3/23 10:25 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$1,296.00	\$0.00
Total Spare Part Cost	\$2,961.87	\$0.00
Total Other Cost	\$620.00	\$0.00
TOTAL COST	\$5,891.87	\$0.00
ump Sum Total	\$5,900.00	\$0.00
Number of Repair Days	7.0	4 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	20/03/2023 10:39 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR REAR PORTION RH	\$1,014.00	400
total Labour	\$1,014.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY REAR BUMPER	\$378.00	200
O RESPRAY FLOOR CORNER PANEL RH	\$180.00	?
O RESPRAY REAR FENDER RH	\$378.00	200
O RESPRAY BUMPER BEAM	\$180.00	NN X
O RESPRAY REAR PANEL	\$180.00	NN X
total Spray Painting & Panel Beating	\$1,296.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	NN X
O WASH AND VACUUM	\$80.00	n X
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00	20
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	NN X
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	50
O REPLACE SUNDRY PARTS	\$100.00	NN X
total Other Costs	\$620.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		58307-47060	END PANEL	1.00	\$755.10	25.00	\$566.33	Replace	R X
		65637-47021	FENDER LINE RR/RH	1.00	\$159.80	25.00	\$119.85	Replace	R X
		52562-47010	TAIL LAMP BRACKET, RH	1.00	\$35.20	25.00	\$26.40	Replace	?
		81551-47180	TAIL LAMP RH	1.00	\$618.60	10.00	\$556.74	Replace	CM ✓
		52159-47905	BUMPER REAR	1.00	\$478.90	25.00	\$359.17	Replace	B ✓
		90467-07211	BUMPER CLIPS (10 PCS)	10.00	\$2.40	25.00	\$18.00	Replace	n ✓
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$234.70	25.00	\$176.02	Replace	R X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	n X
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$108.70	25.00	\$81.53	Replace	n X
		52591-47021	BUMPER SEAL, RR RH	1.00	\$74.40	25.00	\$55.80	Replace	n X
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$155.40	25.00	\$116.55	Replace	n X
		76891-47020	BUMPER LIP REAR	1.00	\$301.90	25.00	\$226.42	Replace	n X
		61601-47090	FENDER RR/RH	1.00	\$980.80	25.00	\$735.60	Replace	R X
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	n X
			STICKER DECAL 65558888	1.00	\$21.80	0.00	\$21.60	Replace	n X
		62710-47130	QUARTER GLASS RR/RH	1.00	\$556.70	25.00	\$417.53	Replace	n X
			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	n X
total					\$4,709.00		\$3,702.34		

Added Spare Parts / Material Usage After Surveyor Signed off

Not Attached
1/1p B

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: