



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS/SPF23002867/Uqy3

ACCIDENT CLAIMS SECTION

Date: 20/03/2023

(SPORE POLICE FORCE)

POLICE LOGISTICS BASE (PLB)

1 HEMMANT ROADSINGAPORE 438675

Code: SPF

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|----------------------|-----------------------|------------|
| Insured Veh. | QX 1924A | Veh. Inspected | SLZ 2065X |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | ACS/105/009/2023/017 | Excess (\$) | 0.00 |
| Assign From | HAFIZUL FARHAN | Assign Date | 20/03/2023 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|--------|---------------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | | |
|-----------------------|---|------------------------|------------|
| Accident Date | 19/03/2023 | Inspection Date | 21/03/2023 |
| Survey held at | FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|