



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:VALE OH			Ref: CC4/HSB23002881/Spa3q2 Date: 19/06/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 3224R	Veh. Inspected	SMX 1996P	
Policy No.	P2478218	Coverage (\$)	0.00	
Claim No.	S3M04KOC	Excess (\$)	0.00	
Assign From		Assign Date	21/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CIVIC TYPE	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	FD21202292	Colour	BLUE	
Odometer	10751 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm	
L/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm	
R/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm	
L/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	15/03/2023	Inspection Date	21/03/2023	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	