

(08/13/13) WPF

ASS. REC. BY: WPF

REF:

CS/UOI 2300 2895 / Rng 3

2947

COE-2023/NOV

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGN 1901Lat Workshop m/s BOENKOof PANDAN CRESCENT

Insured:

UOI

Policy No.

Claims No. M12D00082304

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

(Policy Condition)

CARINS

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

34K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGN 1901L

Yr Regn:

2013 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA LEXUS ES 250 A c.c. 2494

Colour:

MAROON

A/C:

Insured / Std / NI / NA

Sp. Reading

85 693

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTHBJ 164502035389

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/03/23

D.O.I.

21/03/23

Survey held at

BOENKO

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPORT LIMIT - 7K

29/03/23 submit uneconomical total loss

\$9922.70 , check items \$6940.50

mv \$34k

lta \$26132k

nv \$ 7868

Date/Time, File Pass to?

☐

: Prell. Report

1) 29/03/23

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$))

nchcape
 Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No.2 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000018 / 001001 Document No. 0 Document Date 21/03/2023	Dr Tan Seung Po 12 Caldecott Close Singapore 299121 Mobile: 81686611

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2013	ASV60R	BETGK S1	12/11/2013	SGN1901L	0	22318	61UL/SGN1901L/190323

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHBJ1GG502035389	2ARE749994	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z BP-SUNDRY SUNDRIES POLICY NO.:DH0M120025451603 ACC DATE: 19.03.2023 TOW/DRIVE IN:TOWED IN EXCEDATE-IN: 19.03.2023 DATE SURVEY: BY: AUTHORIZED ON:				50 100.00
2	T BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1200 + TOWING CHARGES IF APPLICABLE.				
	Z BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.				
	Z BP-SUNDRY TOWING FROM SCENE OF ACCIDENT				180.00

& on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No.2 Pandan Crescent

Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 46 Robinson Road 02-01 UOI Building Singapore cc	S1000019 / ICUO11	Dr Tan Seung Po 12 Caldecott Close Singapore 299121 Mobile: 81686611
	Document No. 0	
	Document Date 21/03/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2013	ASV60R	BETGK S1	12/11/2013	SGN1901L	0	22318	61UL/SGN1901L/190323

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHBJ1GG502035389	2ARE749994	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON FRONT BUMPER, RHS FRONT FENDER, FRONT DOOR, ROCKER PANEL MOULDING AND FIX NEW PARTS 4960x3				2080 4800.00
B	BP-RES3 TO SPRAY PAINT ON RHS FRONT FENDER, FRONT DOOR, ROCKER PANEL MOULDING AND ROCKER PANEL 816x3				2448 4080.00
B	BP-LAB3 TO REMOVE AND RE-INSTALL FRONT PARKING SENSOR TO ENABLE REPAIR (NETT)				240.00
B	BP-LAB3 TO REMOVE AND RE-INSTALL RHS HEADLAMP TO ENABLE REPAIR. CHECK AND FOCUS HEADLIGHTS (NETT)				240.00
B	BP-MECH3 TO REMOVE AND RE-INSTALL RHS FRONT SUSPENSION TO ENABLE REPAIR AND FIX NEW PARTS				? 1440.00
B	BP-LAB3 TO CARRY OUT WHEEL ALIGNMENT (nETT)				240.00

on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	51000019 / ICU011	Dr Tan Seung Po 12 Caldecott Close Singapore 299121 Mobile: 81686611
	Document No. 0	
	Document Date 21/03/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2013	ASV60R	BETGK S1	12/11/2013	SGN1901L	0	22318	61UL/SGN1901L/190323

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHBJ1GG502035389	2ARE749994	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB3 TO REMOVE, RENEW AND BALANCE RHS FRONT TYRE AND RIM (NETT)				120.00
12	S	BP-SUBLET SUPPLY RHS FRONT TYRE (NETT)				? 800.00
13	Z	BP-SLANT SUPPLY RHS FRONT DOOR SEALANT (NETT)				X 100.00
14	B	BP-LAB3 TO REMOVE AND TRANSFER RHS FRONT DOOR'S COMPONENT AND MECHANISM TO NEW DOOR (NETT)				X 960.00
15	B	BP-ECU3 TO RESET ECU AND REPROGRAMME (NETT)				240.00
16	1	L53811-33230 PANEL, FR FENDER, RH	1.00	1611.00		1611.00
17	2	L53827-33070 PROTECTOR, FR FENDER	1.00	120.40		120.40
18	3	L53875-33220 LINER, FR FENDER, RH	1.00	334.30		334.30
19	4	T90467-07214 CLIP	12.00	3.20		38.40
20	5	L75535-33020 MOULDING	1.00	104.00		104.00
21	6	L75545-30170 CLIP, WINDSHIELD	10.00	12.80		128.00
22	7	L75547-51021 CLIP, WINDSHIELD	10.00	13.10		131.00

*Panel
Hp 900w/68
10-11 days
21/03/23 @1430
EXCESS: TBA*

*Reset
Rego before
paint*

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No.2 Pandan Crescent

Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	51000119 / ICUOI1 Document No. 0 Document Date 21/03/2023	Dr Tan Seung Po 12 Caldecott Close Singapore 299121 Mobile: 81686611

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2013	ASV60R	BETGK S1	12/11/2013	SGN1901L	0	22318	61UL/SGN1901L/190323

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHBJ1GG502035389	2ARE749994	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
23	8	L75851-33912 MOULDING, BODY	1.00	961.30		961.30
24	9	L75867-33050 CLIP, ROCKER PANEL	14.00	12.80		179.20
25	0	L75867-30130 CLIP, ROCKER PANEL	18.00	13.10		235.80
26	1	T43502-28090 HUB SUB-ASSY, FR	1.00	369.70		369.70
27	2	T90369-45003 BEARING	1.00	263.90		263.90
28	3	T43330-39845 JOINT ASSY, LWR	1.00	317.60		317.60
29	4	L48068-33080 ARM SUB-ASSY,	1.00	882.00		882.00
30	5	L43211-33110 KNUCKLE, STEERING	1.00	1158.00		1158.00
31	6	L48510-80676 ABSORBER ASSY, FR RH	1.00	894.80		894.80
32	7	L48820-33070 LINK ASSY, FR	1.00	255.80		255.80
33	8	L67001-33211 PANEL SUB-ASSY, FR	1.00	1550.60		1550.60
34	9	L75985-33030 STRIPE, FR DOOR	1.00	52.40		52.40
35	0	L67861-33100 WEATHERSTRIP, FR	1.00	340.30		340.30
36	1	T67867-12150 RETAINER, DOOR	17.00	6.40		108.80
37	2	L68610-33100 CHECK ASSY, FR DOOR	1.00	330.80		330.80
38	3	L75755-33070 MOULDING, FR DOOR	1.00	117.00		117.00
39	4	L90269-04051 RIVET	13.00	1.80		23.40
40	5	L75071-33120 MOULDING SUB-ASSY,	1.00	207.00		207.00
41	6	L75710-33150 MOULDING ASSY, FR	1.00	207.00		207.00
42	7	L67495-33030 COVER, FR DOOR FR	1.00	97.10		97.10

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	24,559.60
	Please acknowledge receipt of vehicle	Parts 11,019.60 Labour 12,740.00 Sublet 800.00 Lubrication/Fluid 0.00 Others 0.00	GST 8.00%	1,964.77
			Less	0.00
			Amount Due	26,524.37

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third-party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Company Copy

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 294I

Vehicle Details

Vehicle No.: SGN1901L

Vehicle to be Exported: No

Intended Deregistration Date: 21 Mar 2023

Vehicle Make: TOYOTA

Vehicle Model: LEXUS ES250 AUTO

Primary Colour: Brown

Manufacturing Year: 2013

Engine No.: 2ARE749994

Chassis No.: JTHBJ1GG502035389

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$35,305.00

Original Registration Date: 12 Nov 2013

First Registration Date: 12 Nov 2013

Transfer Count: 0

Actual ARF Paid: \$41,427.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 11 Nov 2023

PARF Rebate Amount: \$20,713.00

Intended COE Rebate Details

COE Expiry Date: 11 Nov 2023

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$84,578.00

COE Rebate Amount: \$5,419.00

Total Rebate Amount: \$26,132.00

Lexus ES250

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)**Price****\$55,800****Depreciation** ?

\$22,110 /yr

[View models with similar depre](#)**Reg Date**

27-Oct-2014

(1yr 7mths 5days COE left)

Mileage

110,000 km (13.1k /yr)

Manufactured ?

2014

Road Tax ?

\$1,792 /yr

Transmission

Auto

Dereg Value ?\$34,101 as of today ([change](#))**OMV** ?

\$34,805

COE ?

\$73,010

ARF ?

\$40,727

Engine Cap

2,494 cc

Power

135.0 kW (181 bhp)

Curb Weight ?

1,615 kg

No. of Owners ?

2

Type of Vehicle

Luxury Sedan