

Xin Yu (LKK Auto)

From: Simon Ho (LKKAuto)
Sent: Thursday, April 13, 2023 11:09 AM
To: Xin Yu (LKK Auto)
Subject: Re: File Audit - FBL 7124T - CS3/SMR23002901/Wwy3

Dear Xin Yu,

Audit check done for FBL7124T, found COR range should be 3.5K to 4K with 4 repair days.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Xin Yu (LKK Auto) <xinyu@lkkauto.com>
Sent: Thursday, 13 April 2023 9:29 am
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: File Audit - FBL 7124T - CS3/SMR23002901/Wwy3

Dear Simon,

File for audit check.

Best Regards,

Xin Yu | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | fax: 6256-4315 | email: xinyu@lkkauto.com / sur@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)