



Service Request Details

|              |                                                                                                         |
|--------------|---------------------------------------------------------------------------------------------------------|
| Claim        | S3M04KOE                                                                                                |
| Reference    | CS/HSB23002903/Acp3m4  |
| Loss Date    | 19 March 2023                                                                                           |
| Vendor Name  | LKK AUTO CONSULTANTS<br>PTE LTD (TP)                                                                    |
| Type of Loss | Third Party Vehicle Damage                                                                              |
| Report Date  | 21 Mar 2023 8:50:03 AM                                                                                  |
| Request Date | 21 March 2023                                                                                           |
| Due Date     |                                                                                                         |
| Services     | Pre-Repair Survey                                                                                       |

Actions

Next Step Add invoice

Add Invoice

|                         |          |
|-------------------------|----------|
| Vehicle Information     |          |
| Incident                | SMZ5023K |
| Vehicle                 |          |
| Registration #          |          |
| Make                    | TPVD     |
| Model                   | TBC      |
| Service Address         |          |
| , , ,                   |          |
| Primary Contact/Insured |          |

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

Additional Instructions

Claim Handler

LOW Garnet

garnet.low@axa.com.sg

- Messages3
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

| NAME                                                                                                                                 |                     | DATE UPLOADED              |                                   |               |
|--------------------------------------------------------------------------------------------------------------------------------------|---------------------|----------------------------|-----------------------------------|---------------|
| NAME                                                                                                                                 | TYPE                | SUBTYPE                    | AUTHOR                            | DATE UPLOADED |
|  <a href="#">HSB-LKKInvoice-AC2304049.pdf.pdf</a> | Invoice             | Surveyor/ Assessor expense | LKK AUTO CONSULTANTS PTE LTD (TP) | 23 June 2023  |
|  <a href="#">LKKInspection.pdf.pdf</a>            | Reports & Statement | Survey Report              | LKK AUTO CONSULTANTS PTE LTD (TP) | 23 June 2023  |

| NAME                                                                                                                               | TYPE                | SUBTYPE       | AUTHOR                            | DATE UPLOADED |
|------------------------------------------------------------------------------------------------------------------------------------|---------------------|---------------|-----------------------------------|---------------|
|  <a href="#">LKKAdjustment.pdf.pdf</a>            | Reports & Statement | Survey Report | LKK AUTO CONSULTANTS PTE LTD (TP) | 23 June 2023  |
|  <a href="#">Resurvey photo-2.pdf.pdf</a>         | Evidence            | Photos        | LKK AUTO CONSULTANTS PTE LTD (TP) | 23 June 2023  |
|  <a href="#">Resurvey photo-1.pdf.pdf</a>         | Evidence            | Photos        | LKK AUTO CONSULTANTS PTE LTD (TP) | 23 June 2023  |
|  <a href="#">LKKPhoto.pdf.pdf</a>                 | Evidence            | Photos        | LKK AUTO CONSULTANTS PTE LTD (TP) | 23 June 2023  |
|  <a href="#">After Repair Photographs.pdf.PDF</a> | Evidence            | Photos        | LKK AUTO CONSULTANTS PTE LTD (TP) | 22 June 2023  |
|  <a href="#">Resurvey Photographs.pdf.pdf</a>   | Evidence            | Photos        | LKK AUTO CONSULTANTS PTE LTD (TP) | 22 June 2023  |
|  <a href="#">Photographs.pdf.pdf</a>            | Evidence            | Photos        | LKK AUTO CONSULTANTS PTE LTD (TP) | 22 June 2023  |
|  <a href="#">Immediate Advice.pdf.pdf</a>       | Reports &           | Others        | LKK AUTO CONSULTANTS PTE          | 22 June 2023  |

| NAME                                                                                                                  | TYPE                | SUBTYPE    | AUTHOR           | DATE UPLOADED |
|-----------------------------------------------------------------------------------------------------------------------|---------------------|------------|------------------|---------------|
|                                                                                                                       | Statement           |            | LTD (TP)         |               |
|  PRI TP PDF.pdf.pdf                  | Legal               | Others     | KUMAR Shailendra | 21 March 2023 |
|  PRI TP EMAIL FROM SOLICITOR.msg.msg | Legal               | Others     | KUMAR Shailendra | 21 March 2023 |
|  REPLY FROM TP.msg.msg               | Legal               | Others     | KUMAR Shailendra | 21 March 2023 |
|  OI GIA REPORT - SHC8556A.pdf.pdf    | Reports & Statement | GIA Report | LOW Garnet       | 21 March 2023 |