

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711**Our File No:** CS/III23002908/KNY3E2**Date:** 02/05/2023**REFERENCE**

Insured/Claimant:	TAN YEW WEN CAROL ANN	Policy No:	D19MPC0004890_03
Date of Loss:	12/03/2023	Nature of Claim:	OD
		Claim No:	MPC2023D0003013

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL5321J	Engine No:	3ZRC361658
Make & Model:	TOYOTA RAV4, 2.0 PREMIUM (A)	Chassis No:	JTMDEREV60D123855
Reg. Date:	03/10/2018 (Man. Year: 2018)	Odometer:	30955 km
Colour:	Metallic Grey		
Engine Capacity:	1987 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		5,050.00		
- Excess (S\$)	750.00	750.00	0.00	0.00
Nett Amount (S\$)	-750.00	4,300.00	-5,050.00	673.33

INSPECTION

Date of Assignment:	21/03/2023	
Date Inspected:	24/03/2023	Inspected At: Loh Heng (HQ) 176 Sin Ming Drive, #03-08 Sin Ming Auto Care Singapore 575721
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Apr 2023)

Parts: M1-SUV TOYOTA RAV4 2.0 PREMIUM (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJL5321J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >