Date: 18/04/2023



 $51\, UBI\, AVE\, 1, \#02-25\, PAYA\, UBI\, INDUSTRIAL\, PARK, SINGAPORE\, 408933\, \, TEL: (065)\, 62563561\, \, FAX: (065)\, 62564315$

Immediate Advice

To: ALLIANZ INSURANCE SINGAPORE PTE LTD

Survey Details:

Date of loss	9-Mar-2023
Date of appointment	21-Mar-2023
Date of survey	21-Mar-2023
Location of survey	RYDER AUTO PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM	
Vehicle number	SJK2900M	
Make and Model	MAZDA3 SEDAN 1.5 AT LED EU6	
Date of registration		9-Feb-18
Market Value	\$	65,000.00
Parf Rebate	\$	32,622.00
Nett Loss	\$	32,378.00

Repair details:

Initial Estimate	\$	11,339.07
------------------	----	-----------

Proposed/Revised repair cost:

Parts	\$ 6,147.62
Check items (estimate)	\$ 1
Labour	\$ 1,230.00
Total	\$ 7,377.62
Lump Sum(if applicable)	\$ 5,900.00

Number of days for repair	6.00	est.
---------------------------	------	------

 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,TEL: (065)\,62563561\,FAX: (065)\,62564315$

Remarks:

PD487T (OI) -> SJK2900M (TP)
Liability 100% BOLA 15, at the roundabout OI encroached into TP's lane (TP in
stationary position).

Mandate:

Liability(TP)	100%		
Proposed repair cost	\$	6,372.00	w/GST
Loss of use	\$	480.00	8 days x \$60
Loss of rental	\$	-	
Loss of income	\$	-	
LTA search fees	\$	2.00	
GIA Report fees	\$	31.00	
Proposed Total	\$	6,885.00	