



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: ALLIANZ INSURANCE SINGAPORE PTE LTD 12 MARINA VIEW #04-01, ASIA SQUARE TOWER 2 SINGAPORE 018961	Document No.	: SQT23000857	Page	1
Registration No	: SMM6756R	Date	: 21. Mar 2023		
Chassis No	: MRHFC5650KT000546	Customer No.	: WZA011		
Model	: CIVIC 1.6 VTI YM2019	Svc Advisor	: ANIKKA LAI SWEE KAM		
Owner's Name	: LAI YAOBING NICHOLAS	Engine No	: R16B25510587		
Ins Policy No.	:	Date Time	: 21. Mar 2023 6:42:32 PM		
Date of Accident	: 21/3/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LAI YAOBING NICHOLAS OWNER INSURER: AUTO & GENERAL INS ACC DATE: 21/03/2023 SURVEYED BY: DATE: REF NO: TP INSURER: ALLIANZ TP VEH: SMG7053K						
71101-TEA-T50ZA	FACE,FR.BUMPER	1	579.90	25	434.92	34.79	469.71
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.62	8.42
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.62	8.42
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.38	18.63
71180-TBA-K50	GARNISH ASSY,R.FR.BUMPER SIDE	1	75.90	25	56.92	4.55	61.47
33100-TEC-Q01	HEADLIGHT ASSY,R.	1	675.90	25	506.92	40.55	547.47
				Sum Item	1031.61	82.51	1,114.12
BOSUN	SUNDRIES	1	100.00		100.00	8.00	108.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	160.00		160.00	12.80	172.80
BKBU01R	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	1	1000.00		1000.00	80.00	1080.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	1000.00		1000.00	80.00	1080.00
				Sum Labor	2260.00	180.80	2,440.80

Survey By							
Date & Time				Total Amount	3,291.61	263.31	3,554.92
Excess				Total (Inclusive of GST)			3,554.92

Printed on 21/3/2023 6:51:16 PM
This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.
However, if the repairs are subsequently done at Kah Motor Co, Sdn, Bhd, it will be refunded.
All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.