



VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-136, Enterprise Hub
Singapore 608586

Finalisation

Tel: 6515 9515
claims@vag.sg
www.avantage.sg

Date : 14-Jun-2023

Vehicle Num : SGL7106L

Make/Model : AUDI A6 3.0 TFSI

Chassis No : WAUZZZ4G7BN026252

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear taillamp outer Rh	1	\$ 700.00	\$ 700.00
	TOTAL PARTS			\$ 700.00
	ADDITIONAL 10%			\$ 70.00
	TOTAL AMOUNT			\$ 770.00
	MISCELLANEOUS ITEM			
1	Sundries		\$ 50.00	
	LABOUR			
1	Surface preparation, spray paint and detailing of rear bumper, rear fender Rh and other affected panels		\$ 1,000.00	\$ 600.00
2	Removal and Refitting of rear bumper, rear taillamp Rh, rear fender Rh panel beating and other affected areas		\$ 1,000.00	\$ 500.00
3	To perform diagnostics ,check wire connector and clearing of faults after repair		\$ 80.00	\$ 60.00
	TOTAL			\$ 1,930.00
	GST 8%			\$ 154.40
	GRAND TOTAL			\$ 2,084.40