



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI23002961/Uvy3

Date: 22/03/2023

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 2521J	Veh. Inspected	SMW 7900G
Policy No.		Coverage (\$)	0.00
Claim No.	D23000979MFCV	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	22/03/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	18/03/2023	Inspection Date	22/03/2023
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--