Date: 12/4/2023



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$

Immediate Advice

To: ALLIANZ INSURANCE SINGAPORE PTE LTD

Survey Details:

Date of loss	15-Mar-2023
Date of appointment	22-Mar-2023
Date of survey	22-Mar-2023
Location of survey	2ND AUTO PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GBK605Z
Make and Model	TOYOTA HIACE DX (2982cc)
Date of registration	29-Jun-1
Market Value	\$ 35,000.0
Parf Rebate	\$ 12,945.0
Nett Loss	\$ 22,055.0

Repair details:

Initial Estimate	\$	12,273.00
IIIIllai Liiiilale	ې	12,273.00

Proposed/Revised repair cost:

Parts	\$ 4,765.33
Check items (estimate)	NIL
Labour	\$ 1,950.00
Total	\$ 6,715.33
Lump Sum(if applicable)	\$ 5,300.00

Number of days for repair	5.00	est.
---------------------------	------	------



 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,TEL: (065)\,62563561\,FAX: (065)\,62564315$

Remarks:

OI HIT ON THE REAR PORTION OF THE TP VEHICLE.			

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 5,300.00	\$ 5,300.00
Loss of Use (7DAYS X \$80.00)	\$ 560.00	NIL
Loss of Rental (7DAYS		
X\$100.00)(w/GST)	NIL	\$ 756.00
Loss of Income	NIL	NIL
LTA/GIA search fees	\$ 26.75	\$ 26.75
Others	NIL	NIL
Proposed Total	\$ 5,886.75	\$ 6,082.75