

Meng Yan (LKK Auto)

From: Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Wednesday, 22 March 2023 9:35 AM
To: assignments
Cc: SUR
Subject: OD survey assignment for XE3186S - DOA : 27/01/2023 Our Ref: 2300023/HLF

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	:	XE3186S		
Policy Number	:	BVF2SB0002812200	Account Code:	B368SD0
Policy Excess	:	\$ 2,000	(Allied World waived \$) (Insured to pay \$)	
Voluntary Excess	:	\$	(No waiver)	
Sum Insured	:	Market Value with COE & PARF		
Make / Model	:	MITSUBISHI FUSO FP51SDR3VDEA PRIME MOVER		
Name of Workshop	:	GOLDBELL ENGINEERING PTE LTD		
Contact Number	:	9739 7127		
Person to Contact	:	MR LIEW SI MING		
Estimated Cost of repairs	:	\$ 19,739.20		
(x)	Please take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera. (Compulsory)			
(X)	Please revert with your preliminary survey report with photographs			

Regards,

Claims Division

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, Ltd or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.