



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				CS3/INC23001026/Wqy3-1	
INCOME INSURANCE LTD				Ref: CS/INC23001026/Wqy3	
75 BRAS BASAH ROAD				Date: 01/02/2023 20/03/2023	
INCOME CENTRESINGAPORE 189557				Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
Insured Veh.	SLG 7164K	Veh. Inspected	SMP 5607D		
Policy No.		Coverage (\$)	0.00		
Claim No.	MT/1207770-002	Excess (\$)	0.00		
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	01/02/2023 20/03/2023		
2. Vehicle Particulars & Condition					
Make & Model		c.c	0		
Engine No.	HIDDEN	Year of Reg.			
Chassis No.		Colour			
Odometer	-	Steering			
Brakes		Modification			
General					
3. Conditions of Tyres					
	Size	Make	Balance		
R/H Front Tyre			mm		
L/H Front Tyre			mm		
R/H Rear Tyre			mm		
L/H Rear Tyre			mm		
4. Description of Damages					
5. General Information					
Accident Date	30/01/2023	Inspection Date	01/02/2023		
Survey held at	BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 451875				
Repairer	SHIFTER AUTO GARAGE PTE LTD				
5a. Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					