

AUTOSPRINT PTE LTD

UEN No.: 201729594D GST Reg. No.: 201729594D 24 Leng Kee Road #07-02B/C/D Leng Kee AutoPoint Singapore 159096

Tel: 6911 8338 Fax: 6251 7438 Email: enquiry@autosprint.com.sg

QUOTATION

To: Asad Alamgir Haque

SMJ5995P, TOYOTA, ESQUIRE HYBRID 7-SEATER 1.8GI CVT

Our Ref :Q230305 Date :21 Mar 2023

Attn: Asad Alamgir Haque (93891142)

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Remarks :T/Party claims SMJ5995P against SMD1646E

No.	Description	Qty UOM	U/P (S\$)	Amt (S\$)
	Ad hoc			
1	Rear Boot Cover	1.00	1,020.00	1,020.00
2	Rear Boot Inner Lock	1.00	473.50	473.50
3	Rear Boot Weatherstrip	1.00	228.00	228.00
4	Rear Boot Emblem	1.00	43.75	43.75
5	Rear Boot R/H Chrome Moulding	1.00	525.00	525.00
6	Rear Bumper	1.00	420.00	420.00
7	Rear Bumper Retainers & Clips	1.00	120.00	120.00
8	Rear Windscreen Moulding	1.00	160.00	160.00
9	Rear Windscreen Sealant	1.00	80.00	80.00
10	Rear Windscreen Solar Film	1.00	150.00	150.00
11	Labour Charge to straighten rear lower inner panel, remove & replace the above listed damaged parts	1.00	1,200.00	1,200.00
12	Labour Charge to reconnect rear wire hardness & check for proper function	1.00	50.00	50.00
13	Labour Charge to remove & reinstall/replace rear windscreen glass	1.00	140.00	140.00
14	Labour Charge to putty & spray painting on the affected parts & areas.	1.00	900.00	900.00
15	Rear Bumper Reverse Sensors	1.00	180.00	180.00

I have read and agree to the terms and conditions stated in the reverse side of this quotation and authorise AUTOSPRINT Pte Ltd to carry out the above work described. Additional quotation (if any) on subsequent repair found during inspection and diagnostics may be provided.

> Subtotal: GST 8.0% : Total Amount:

5,690.25 455.22 6,145.47