



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:WINNIE		Ref: CC4/HSB23003028/Upa3q2 Date: 18/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJQ 4155C	Veh. Inspected	SKQ 6257S
Policy No.	GA540749	Coverage (\$)	0.00
Claim No.	S3M04KTI	Excess (\$)	0.00
Assign From		Assign Date	23/03/2023
2. Vehicle Particulars & Condition			
Make & Model	AUDI A3 (A)	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WAUZZZ8V1F1054523	Colour	WHITE
Odometer	178021 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55Z R16	MICHELIN	6 mm
L/H Front Tyre	205/55Z R16	MICHELIN	6 mm
R/H Rear Tyre	205/55Z R16	MICHELIN	6 mm
L/H Rear Tyre	205/55Z R16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/03/2023	Inspection Date	23/03/2023
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	