

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC23003069/Avy3m4	
	75 BRAS BASAH R INCOME CENTRES	OAD SINGAPORE 189557		Date:	19/05/2023	
	ATTN: RAJESWAR	Y		Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMX 5170D	Veh. Inspected	ł	SNE 2018U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1215289-001	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		23/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA NOAH HYBRID	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2022	
	Chassis No.	ZWR800507928	Colour		WHITE	
	Odometer	63306 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65R15	GREENLANDER	•	6 mm	
	L/H Front Tyre	195/65R15	GREENLANDER		6 mm	
	R/H Rear Tyre	195/65R15	GREENLANDER		6 mm	
	L/H Rear Tyre	195/65R15	GREENLANDER		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
					1.0	
5.	General Information					
	Accident Date	17/03/2023	Inspect Date /	Time	03/04/2023 (10:55 AM)	
	Survey held at	AUTO UNITED SG PTE LTD				
	-	13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					
L						