



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23003080/Uqy3e2	
			Date: 12/04/2023	
			Code: SMO	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	Insured Veh.		Veh. Inspected	SKT 5575P
	Policy No.	D22MTPV01008791	Coverage (\$)	0.00
	Claim No.	CMTD2301166/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	24/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA MOBILIO SV (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	MRHDD4870FP000133	Colour	WHITE
	Odometer	169507 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	185/65 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	185/65 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	185/65 R15	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	21/03/2023	Inspection Date	24/03/2023
	Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE MARKET VALUE IS S\$34,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	