



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2304736

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 24/07/2023
Reference CS3/III23003084/Sqy3e2
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 8567C

Insured Veh. SLQ 9337M

Claim No.

Policy No.

Accident Date 03/03/2023

Inspection Date 27/03/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 27.03.2023 03.00pm	
- Dismantle Inspection 21.04.2023 08.51am	
- After Repair Inspection 26.04.2023 04.01pm	
Merimen Fee	11.00
Subtotal	131.00
GST (8%)	10.48
Grand Total	141.48

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM