

李 汽 车 贸 易

GST REG NO. 201918537M

# ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

## ESTIMATE COST OF REPAIR

Date: 22-Mar-23

Estimate no.

1234

Plate No. FBM3382K

Model. HONDA CB400X

\*Surveyor's columns\*

| S/N | DESCRIPTION (s)                | PRICE (\$) | REMARK | PRICE (\$) |
|-----|--------------------------------|------------|--------|------------|
| 1   | REAR FENDER CRA                | \$ 280.00  | 170    |            |
| 2   | REAR NUMBER PLATE CRA          | \$ 2030.00 | -      |            |
| 3   | REAR SIGNAL LIGHT LEFT SCRA    | \$ 180.00  | 100    |            |
| 4   | REAR SIGNAL LIGHT RIGHT SCRA   | \$ 180.00  | 100    |            |
| 5   | EXHAUST PIPE SCRA R            | \$ 950.00  | X      |            |
| 6   | EXHAUST COVER SCRA             | \$ 280.00  | 150    |            |
| 7   | REAR PILLION BAR LEFT SCRA     | \$ 220.00  | 200    |            |
| 8   | REAR PILLION BAR RIGHT SCRA    | \$ 220.00  |        |            |
| 9   | BODY UNDER COVER RIGHT SCRA    | \$ 200.00  | 160    |            |
| 10  | CRASH BAR SCRA                 | \$ 450.00  | 380    |            |
| 11  | HANDLE BAR Pnt                 | \$ 380.00  | 180    |            |
| 12  | HANDLE BALANCER SCRA           | \$ 150.00  | 60     |            |
| 13  | MIRROR RIGHT SCRA              | \$ 150.00  | 95     |            |
| 14  | BRAKE LEVER RIGHT SCRA         | \$ 120.00  |        |            |
| 15  | FRONT FAIRING COVER RIGHT SCRA | \$ 400.00  | 180    |            |
| 16  | MIRROR LEFT X NN               | \$ 150.00  | X      |            |
| 17  | CLUTH LEVER X NN               | \$ 120.00  | X      |            |
| 18  | LABOUR 250                     | \$ 500.00  | 250    |            |
| 19  | Spray cover set                | \$ 450     | 200    |            |

20 rear handle seat bar RH \$180. cur ✓

21 rear slider RH \$75 cur ✓

Sub Total : \$

GST 8% \$

Total: \$

4,960.00

4,464.00

357.12

4,821.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part's prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed  
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

\*Estimate given are base on visible damages ONLY before dismantling of the Vehicle\*

\*This is computer generated no signature is required.\*

5165

2-2170

102

1953

450

2403

282

1922