

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

) \$ + RS. \$ SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$)

30/3/23 No second hand parts
PIP \$1699.20 insured MR Tan

TLM Automobile Pte Ltd**1 Defu Lane 6 Singapore 539365****UEN number: 202244624K**

Ms Lim Ai Yean

Third Party Insurer: Allianz Insurance

Date of accident : 18 Mar 2023

Date: 27 Mar 2023

Estimate To Repair

SMP834Y - HYUNDAI AD AVANTE 1.6 GLS A

Chassis No : KMHD841CMKU804008

not allowed
her

27/3/23

urgent before party CLK

3 days

P/P #1699-20 27/3/2023 @

S/No	Quantity	Description	Amount
LIST ITEMS			
1	1 pc	Rear bumper 75	\$ 450.00
2	10 pc	Rear bumper clips @ \$3.50 22	\$ 35.00
3	1 pc	Rear bumper reinforcement 11	\$ 295.00
4	2 pc	Rear bumper reinforcement bracket @ \$78.00 11	\$ 156.00
5	2 pc	Rear bumper side retainer @ \$27.00 11	\$ 54.00
6	2 pc	Rear bumper under splash guide @ \$38.00 11	\$ 76.00
7	12 pc	Rear bumper under splash guide clips @ \$4.50 11	\$ 54.00
8	1 pc	Rear bumper outer garnish 2.5	\$ 354.00
9	2 pc	Rear bumper reflector @ \$210.00 2/3 one o/s 11	\$ 420.00
10	1 pc	Rear end panel 11	\$ 460.00
11	1 pc	Rear end panel top garnish 11	\$ 159.00
12	1 pc	Rear licence plate garnish 11	\$ 98.00
13	2 pc	Rear bumper lower bracket @ \$27.00 11	\$ 54.00
14	1 pc	Bootlid keyless sensor 11	\$ 360.00
15	1 pc	Bootlid keyless sensor antenna (buzz) 11	\$ 105.00
16	1 pc	Rear bootlid cover 11	\$ 2,050.00
17	1 pc	Rear bootlid inner lock 11	\$ 305.00
18	1 pc	Rear bootlid rubber 11	\$ 156.00
19	1 pc	"H" emblem 11	\$ 95.00
20	1 pc	"AVANTE" emblem 11	\$ 85.00
			\$ 5,821.00
Less 20%			\$ 1,164.20
			\$ 4,656.80
SPECIAL NETT ITEMS			
21	1 set	Rear reverse sensor 24	\$ 250.00
22	1 pc	Rear number plate 24 n/c	\$ 50.00
			\$ 300.00
Balance c/f			\$ 4,956.80

TLM Automobile Pte Ltd
1 Defu Lane 6 Singapore 539365
UEN number: 202244624K

Ms Lim Ai Yean

Third Party Insurer: Allianz Insurance

Date of accident : 18 Mar 2023

Date: 27 Mar 2023

Estimate To Repair

SMP834Y - HYUNDAI AD AVANTE 1.6 GLS A

Chassis No : KMHD841CMKU804008

S/No	Quantity	Description	Amount
		Balance b/f	\$ 4,956.80
		<u>LABOUR & MISC. CHARGES</u>	
1		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 80.00
2		To rust-proofing of the affected areas.	\$ 120.00
3		To check electrical lighting concerned.	\$ 80.00
4		To remove and reinstall reverse camera.	\$ 80.00
5		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00
6		Putty and spray painting of the affected portion.	\$ 850.00
			\$ 2,010.00
		Grand Total	\$ 6,966.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

X
X
20
40
400
400
P- 1049
20%
839.2
860
1699.2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 745I

Vehicle Details

Vehicle No.: SMP834Y

Vehicle to be Exported: No

Intended Deregistration Date: 27 Mar 2023

Vehicle Make: HYUNDAI

Vehicle Model: AD AVANTE 1.6 GLS (A)

Primary Colour: Red

Manufacturing Year: 2018

Engine No.: G4FGJU033693

Chassis No.: KMHD841CMKU804008

Maximum Power Output: 93.8 kW (125 bhp)

Open Market Value: \$12,338.00

Original Registration Date: 10 Sep 2019

First Registration Date: 10 Sep 2019

Transfer Count: 2

Actual ARF Paid: \$12,338.00 6169

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 09 Sep 2029

PARF Rebate Amount: \$9,253.00

Intended COE Rebate Details

COE Expiry Date: 09 Sep 2029

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$26,309.00

COE Rebate Amount: \$16,975.00

Total Rebate Amount: \$26,228.00

The information contained herein is correct as at 27 Mar 2023

OK

