

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (C)

Vehicle No:	SLS4077K (Insd veh)	Model:	TOYOTA HIACE 3.0 DX DIESEL
	CB7463E (TP veh)		TBO AT 2WD 3.0 D (A)
Date of Accident:	22/03/2023		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				4,304.74
Final Repair Cost	:	\$				670.00
Loss of Use	:	\$				200.00
						2.00 days at \$100.00 per day
Rental (if any)	:	\$				0.00
						days
LTA / GIA Search Fee	:	\$				26.75
Others:	:	\$				0.00
	:	\$				
Final Settlement Sum	:	\$				896.75

Is Third Party Workshop GIA Registered?				[]	YES	[X]	NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u>:				Agreed Liability _____ 100 _____ (%)				
B) For <u>GIA Registered Workshop</u>:				BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ (%)				
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	Zero Gravity	:	896.75
2)		:	
3)		:	

JOANNE LEE KHANG MIN

05 Jul
2023

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))