



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                 |  |           |
|--|--|-----------------|--|-----------|
| AUTO & GENERAL INSURANCE (S) PL<br>(BUDGET DIRECT INSURANCE)<br>190 CLEMENCEAU AVENUE #03-01<br>SINGAPORE SHOPPING CENTRESINGAPORE<br>239924 |  |                 | Ref: CS/AGI23003114/Kwy3q2<br>Date: 04/04/2023 | Code: AGI |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                 |  |           |
| Insured Veh.   | SLJ 1130G  | Veh. Inspected  | SHD 404C                                       |           |
| Policy No.   | P10101646R04   | Coverage (\$)   | 0.00   |           |
| Claim No.  | C10021248/JY   | Excess (\$)     | 0.00   |           |
| Assign From  | DON BONG   | Assign Date     | 27/03/2023                                     |           |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                 |  |           |
| Make & Model   | RENAULT LATITUDE (A)   | c.c             | 1995   |           |
| Engine No.   | HIDDEN   | Year of Reg.    | 2016   |           |
| Chassis No.  | VF1ABL15AUC283446  | Colour          | METALLIC WHITE / RED                           |           |
| Odometer   | 735761 KM  | Steering        | IN ORDER                                       |           |
| Brakes   | IN ORDER   | Modification    | NIL  |           |
| General  | GOOD   |                 |  |           |
| <b>3. Conditions of Tyres</b>  |  |                 |  |           |
|  | Size   | Make            | Balance  |           |
| R/H Front Tyre   | 215/60 R16   | GRENLANDER      | 9 mm   |           |
| L/H Front Tyre   | 215/60 R16   | GRENLANDER      | 9 mm   |           |
| R/H Rear Tyre  | 215/60 R16   | FIRENZA         | 8 mm   |           |
| L/H Rear Tyre  | 215/60 R16   | FIRENZA         | 8 mm   |           |
| <b>4. Description of Damages</b>   |  |                 |  |           |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.<br>DAMAGES SEE DETAILS.   |  |                 |  |           |
| <b>5. General Information</b>  |  |                 |  |           |
| Accident Date  | 24/03/2023   | Inspection Date | 27/03/2023                                     |           |
| Survey held at   | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                 |  |           |
| <b>5a. Remarks</b>   |  |                 |  |           |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.       |  |                 |  |           |
| <b>5b. Estimate Days of Repair</b>   |  |                 |  |           |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  |                 | 8 Working Days                                 |           |