

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**27 MAR 2023**

Estimate No. : b1 65431
Date Estimated : 25/03/2023
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Tong Jun Lin (Zhong Yunling)
32 West Coast Rise
West Coast Gardens

Singapore 127475

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA828C	WBAJA52010G885227	26/04/2017	530iA	29209

DESCRIPTIONVALUE

To replace rear bumper, tail end panel, bootlid and all damage parts

2550 5,100.00

To respray rear bumper, bootlid and tail end panel

1972 2,819.00

To carry out body cavity preservation.
(Per panel).

112 118.00

To carry out body cavity preservation.
(For cut panel).

504? 531.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

168 177.00

To check electrical wiring

168 177.00

To transfer lock mechanism from old to new bootlid
including conduct check on new bootlid central locking system
for proper function.

504 531.00

To replace rear exhaust silencer including alignment
system and conduct check for leak.

504? 531.00

To replace front exhaust silencer including alignment
system and conduct check for leak.

504? 531.00

Sundries.

? 150.00

Total Labour 1: **10,665.00**DESCRIPTIONQTYPRICVALUE

CLAMPING BUSH

1 73.10

73.10

TAILPIPE TRIM CHROME

2 156.55

313.10

FRONT SILENCER

1 1,655.15

1,655.15

INTERMEDIATE PIPE

1 624.90

624.90

LHx, RH del

X

?

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 65431
Date Estimated : 25/03/2023
Prepared By : Jack Ng Guo Ming

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA828C	WBAJA52010G885227	26/04/2017	530iA	29209

DESCRIPTION	QTY	PRIC	VALUE
REAR SILENCER WITH EXHAUST FLAP	1	2,077.80	? 2,077.80
COMPLETE TAIL TRIM	1	890.05	? 890.05
TAILGATE ALUMINIUM	1	1,901.25	bl- 1,901.25
OUTER PANEL TAIL TRIM	1	607.50	? 607.50
REAR BUMPER CARRIER	1	936.90	? 936.90
REAR BUMPER BOTTOM REINFORCEMENT	1	151.90	? 151.90
REAR BUMPER CENTRE GUIDE	1	179.90	? 179.90
REAR BUMPER LH SIDE GUIDE	1	192.75	X 192.75
REAR BUMPER RH SIDE GUIDE	1	179.90	? 179.90
REAR BUMPER TRIM STRIP	1	107.35	? 107.35
REAR BUMPER PANEL PRIMED (PDC/PMA)	1	1,664.50	de- 1,664.50
TRUNK LID GASKET	1	135.15	? 135.15
REAR LH LIGHT IN THE SIDE PANEL	1	670.30	X 670.30
REAR RH LIGHT IN THE SIDE PANEL	1	670.30	? 670.30
REAR LH LIGHT IN TRUNK LID	1	395.90	X 395.90
REAR RH LIGHT IN TRUNK LID	1	395.90	? 395.90

Total Parts : 13,823.60

Tanpin 92445749/62585561
wp 10/4/23
p/p Remy bfor paint
tanpin e/whanta.com
06 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	10,665.00
Parts	:	13,823.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	1,959.09
Grand Total	:	26,447.69

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **