



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI23003139/Rqy3e2 Date: 27/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 6316B	Veh. Inspected	SNH 6577E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D23001051MFBP	Excess (\$)	0.00	
Assign From	JOANNE TAN JO ANN	Assign Date	27/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	BYD E6	c.c	0	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	LC0CE4DC1N0371496	Colour	BLACK	
Odometer	9008 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	CHAO YANG	6 mm	
L/H Front Tyre	215/55 R17	CHAO YANG	6 mm	
R/H Rear Tyre	215/55 R17	CHAO YANG	6 mm	
L/H Rear Tyre	215/55 R17	CHAO YANG	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/03/2023	Inspection Date	31/03/2023	
Survey held at	VANTAGE AUTOMOTIVE LIMITED 305 ALEXANDRA ROAD, #02-01, VANTAGE AUTOMOTIVE CENTRE, SINGAPORE 159942			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	