



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts Er	n Automol	bile	
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CS3/CTI23003140/p3	
	3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date:	27/03/2023	
	SPRINGLEAF TO	VERSINGAPORE 079909		0 1	OTI	
4		Daliau Dautiaulaus	/TUDD DADTY	Code:	CTI	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SML 5277T	Veh. Inspected	1	BICYCLE	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM23D201915/C02	Excess (\$)		0.00	
	Assign From	TAN KAH LEONG	Assign Date		27/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	Year of Reg.				
	Chassis No. Colour					
	Odometer - Steerii			eering		
	Brakes Modification					
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	12/03/2023	Inspection Dat	e		
	Survey held at	BYX THE BICYCLE COMPANY				
	403 RIVER VALLEY ROAD, SINGAPORE 248301					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					