LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

From:

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three

Paya Ubi Industrial Park Singapore 038988 Singapore 408933

Attn: 18 Apr 2023 Date:

Preliminary Advice

Insured Vehicle No : SMV3883D

TP Vehicle No : SHF564M Accident Date : 23/03/2023 Make : TOYOTA PRIUS Assignment Date : 27/03/2023 Date of Inspection : 27/03/2023 Est. Duration of Repair : 4 days

Inspection At : TRANS-CAB AUTO SERVICES PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,412.26
Revised Amount	:S\$	5,892.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,892.88

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let
		us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments:

The above survey was conducted on a 'Without Prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.