



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23003148/Uny3e2 Date: 05/04/2023 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMC 1207U	Veh. Inspected	SMS 5312M
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10021251 /CH	Excess (\$)	0.00
	Assign From	FRAULEINE KHOO	Assign Date	27/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLC300 AMG LINE M-HYBRID (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WDC2533842F730380	Colour	GREY
	Odometer	79605 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R19	MICHELIN	6 mm
	L/H Front Tyre	235/55 R19	MICHELIN	6 mm
	R/H Rear Tyre	255/50 R19	MICHELIN	6 mm
	L/H Rear Tyre	255/50 R19	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/03/2023	Inspection Date	27/03/2023
	Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	