

(08/15/13) wof

ASS. REC. BY: John

REF:

CS/EA123003150/R943

737A

ASSIGNMENT

C08-229/MAY

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: 8JR 9925Jat Workshop m/s MOVAof PAUL T MURPHYInsured: EA1

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 65K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8JR 9925J Yr Regn: 2009 July

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I30 1.6 Doka A c.c. 1591Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 101846 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHDCSIDR94187074

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 3/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / OKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 22/03/23

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 03/04/23Survey held at MOVA

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 47K

Date/Time, File Pass to?



: Prell. Report

1) _____



: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

22/3/2023

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Vehicle No: SJR9925J
Vehicle Model: HYND I30
Est No: CD2327
Claims ref:
Accident Date: 22/03/23
In Charge: BILLY
Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	RADIATOR GRILLE ?	1	PC \$ 82.10	\$ 82.10
2	RADIATOR GRILLE LOGO ?	1	PC \$ 23.00	\$ 23.00
3	HEADLAMP ASSY RH & LH X	2	PC \$ 606.20	\$ 1,212.40
4	FRONT BUMPER repair	1	PC \$ 456.70	\$ 456.70
5	FRONT BUMPER GRILLE - CENTER ?	1	PC \$ 53.20	\$ 53.20
6	FRONT BUMPER SPONGE ?	1	PC \$ 82.10	\$ 82.10
7	FRONT BUMPER REINFORCEMENT ?	1	PC \$ 279.60	\$ 279.60
8	FRONT BUMPER RETAINER RH & LH X	2	PC \$ 26.00	\$ 52.00
9	FRONT BUMPER CLIPS ne -	10	PC \$ 3.00	\$ 30.00
10	TAILGATE bt	1	PC \$ 2,045.70	\$ 2,045.70
11	TAILGATE GLASS MOULDING ne -	1	PC \$ 65.00	\$ 65.00
12	TAILGATE EMBLEM - HYUNDAI ne -	1	PC \$ 25.40	\$ 25.40
13	TAILGATE EMBLEM - I30 ne -	1	PC \$ 28.70	\$ 28.70
14	TAILGATE EMBLEM - S ne -	1	PC \$ 55.00	\$ 55.00
15	TAILGATE LOCK X	1	PC \$ 166.80	\$ 166.80
16	TAILGATE WEATHERSTRIP ne -	1	PC \$ 84.80	\$ 84.80
17	TAILAMP ASSY RH & LH ?	2	PC \$ 550.10	\$ 1,100.20
18	REAR END PANEL bt	1	PC \$ 499.30	\$ 499.30
19	REAR END PANEL TOP COVER ?	1	PC \$ 30.20	\$ 30.20
20	REAR BUMPER de	1	PC \$ 517.10	\$ 517.10
21	REAR BUMPER SPONGE ?	1	PC \$ 129.30	\$ 129.30
22	REAR BUMPER REINFORCEMENT ca	1	PC \$ 270.00	\$ 270.00
23	REAR BUMER RETAINER RH & LH ne	2	PC \$ 26.00	\$ 52.00
24	REAR BUMPER CLIPS ne	10	PC \$ 3.00	\$ 30.00
25	REAR BUMPER BRACKET RH & LH ?	2	PC \$ 79.20	\$ 158.40
26	REAR TOW COVER X	1	PC \$ 10.00	\$ 10.00
LIST TOTAL S\$				\$ 7,539.00
20% DISCOUNT S\$				\$ (1,507.80)
				<u>\$ 6,031.20</u>

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

22/3/2023

EQ INSURANCE CO LTD

5 MAXWELL ROAD

#17-00 TOWER BLOCK MND COMPLEX

SINGAPORE 069110

Vehicle No: SJR9925J
Vehicle Model: HYND I30
Est No: CD2327
Claims ref:
Accident Date: 22/03/23
In Charge: BILLY
Remarks:

No	Description	Qty	U. Price	Amounts S\$
----	-------------	-----	----------	-------------

SPECIAL NET ITEMS:

1	FRONT NUMBER PLATE <i>can</i>	1	PC	40.00	\$	40.00 35
2	TAILGATE GLASS SEALANT <i>re</i>	1	PC	40.00	\$	40.00 ✓
3	REAR NUMBER PLATE <i>lt</i>	1	PC	40.00	\$	40.00 35
4	REVERSE SENSOR <i>X</i>	1	PC	200.00	\$	200.00 X

SPECIAL NET TOTAL S\$

\$ 320.00

LABOUR CHARGE:

1	TO CUT & WELD REAR END PANEL, KNOCK & STRAIGHTEN FRONT & REAR BODY MEMBERS, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	\$	1,000.00 900
2	SPRAY PAINT FRONT BUMPER, TAILGATE, REAR END PANEL, REAR BUMPER	\$	800.00 ✓
3	REMOVE & REPLACE TAILGATE GLASS & CHECK WATER LEAKAGE	\$	120.00 ✓
4	REMOVE & REPLACE TAILGATE INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM	\$	60.00 40
5	REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION	\$	60.00 40
6	RUST PROOF AFFECTED AREAS	\$	60.00 ✓

TOTAL LABOUR COST S\$

\$ 2,100.00

ESTIMATE

22/3/2023

EQ INSURANCE CO LTD
 5 MAXWELL ROAD
 #17-00 TOWER BLOCK MND COMPLEX
 SINGAPORE 069110

Vehicle No: SJR9925J
 Vehicle Model: HYND I30
 Est No: CD2327
 Claims ref:
 Accident Date: 22/03/23
 In Charge: BILLY
 Remarks:

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
AMOUNT S\$				\$ 8,451.20
GST @ 8%				\$ 676.10
AMOUNT DUE S\$				\$ 9,127.30

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 9601068
8 days
4/8
03/04/23 @ 1530
Revy after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	737A

Vehicle Details

Vehicle No.:	SJR9925J
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	I30 (FD) 1.6 DOHC AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U670554
Chassis No.:	KMHDC51DR9U187074
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$13,717.00
Original Registration Date:	25 Jul 2009
First Registration Date:	25 Jul 2009
Transfer Count:	0
Actual ARF Paid:	\$13,717.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 May 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$27,886.00
COE Rebate Amount:	\$17,173.00
Total Rebate Amount:	\$17,173.00

Hyundai i30 1.6A (COE till 09/2029)

Overview	Insurance	Financial	Accessories	Similar	Research	Photos	Mileage
Price	\$69,800						
Depreciation 	\$10,750 /yr		Reg Date		28-Sep-2009 (6yrs 5mths 24days COE left)		
Mileage	N.A.		Manufactured 		2009		
Road Tax 	\$1,033 /yr		Transmission		Auto		
Dereg Value 	\$19,137 as of today (change)		OMV 		\$13,269		
COE 	\$29,485		ARF 		\$13,269		
Engine Cap	1,591 cc		Power		89.7 kW (120 bhp)		
Curb Weight 	1,314 kg		No. of Owners		4		
Type of Vehicle	Hatchback						