

ASS. REC. BY:

REF:

C72/23 003197/kp

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

11:30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PNG 4711C

Yr Regn:

08, 22

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

m. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

79835

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTD8S3EU30J008544

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/80R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nailun

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

25/3/23

D.O.I.

28/3/2023

Survey held at

Des. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/3 11:30am 815000 Car

Data/Time, File Pass to?

☐

: Prell. Report

1)

Data/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Parking

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



Date: 27/03/2023

Vehicle No: SNG4711C

Model: TOYOTA PRIUS PLUS

Chassis: JTDZS3EU30J068544-2021

Reg.Year: 2022

*Not Withdrawn  
11 Pym & 1500ph*

*Heavy Acc Repair*

*2 days*

Third Party Insurer: CHINA TAIPING

Third Party Veh No: YM7122X

Date of Accident: 25/03/2023

Estimator: TING AN

Surveyor:

## ESTIMATE

| NO.         | DESCRIPTION                 | QTY | UNIT S\$ | AMOUNT S\$          |
|-------------|-----------------------------|-----|----------|---------------------|
| 1           | REAR BUMPER <i>341.10</i>   | 1   |          | <i>Be</i> \$549.00  |
| 2           | REAR BUMPER LOWER LIP       | 1   |          | <i>n</i> \$726.00   |
| 3           | REAR BUMPER SIDE BRACKET LH | 1   |          | <i>P.1</i> \$144.00 |
| 4           | REAR BUMPER REFLECTOR LH    | 1   |          | <i>rn</i> \$75.00   |
| 5           | REAR BUMPER REINFORCEMENT   | 1   |          | <i>Ry</i> \$205.00  |
| SUB TOTAL   |                             |     |          | \$1,699.00          |
| LESS 25%    |                             |     |          | -\$424.75           |
| PARTS TOTAL |                             |     |          | \$1,274.25          |

| NO.       | SPECIAL NETT               | QTY | UNIT S\$ | AMOUNT S\$        |
|-----------|----------------------------|-----|----------|-------------------|
| 1         | REAR BUMPER CLIPS          | 1   |          | <i>n</i> \$50.00  |
| 2         | REAR BUMPER REVERSE SENSOR | 1   |          | <i>n</i> \$300.00 |
| S/N TOTAL |                            |     |          | \$350.00          |

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

*200*  
\$300.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC.

*200*  
\$300.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

*50*  
\$120.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

*n* \$100.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

*n* \$80.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), during resurvey
- Parts prices are subject to confirmation
- Third party claims are on a non-liable basis
- No illegal modification allowed
- Supplementary repairs must be resurveyed and approved by the insurance company

LABOUR TOTAL \$900.00

TOTAL \$2,524.25

TING AN

#### Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 4011

