



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23003199/Kny3e2 Date: 20/06/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5347L	Veh. Inspected	SLT 6041U
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/03/23/2050	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	28/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	RU31226115	Colour	METALLIC GOLD
	Odometer	407689 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	TRIANGLE	8 mm
	L/H Front Tyre	215/60 R16	TRIANGLE	8 mm
	R/H Rear Tyre	215/60 R16	FIRENZA	4 mm
	L/H Rear Tyre	215/60 R16	FIRENZA	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/03/2023	Inspection Date	29/03/2023
	Survey held at	BLK 385 SIN MING DRIVE		
	Repairer	ESTEEM PERFORMANCE PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	