



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SINGAPORE CIVIL DEFENCE FORCE (MHA05)			Ref:	CS/SCD23003205/Rqy3e2
91 UBI AVE 4 SINGAPORE 408827			Date:	24/05/2023
ATTN: RALF TAY			Code:	SCD
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 2507P	Veh. Inspected	SHA 8472T	
Policy No.		Coverage (\$)	0.00	
Claim No.	2023 - 35	Excess (\$)	0.00	
Assign From	RALF TAY	Assign Date	28/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI AE IONIQ HEV 1.6	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHC851CVJU103740	Colour	YELLOW	
Odometer	351584 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	TRIANGLE	6 mm	
L/H Front Tyre	195/55 R15	TRIANGLE	6 mm	
R/H Rear Tyre	195/55 R15	TRIANGLE	6 mm	
L/H Rear Tyre	195/55 R15	TRIANGLE	6 mm	
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
Accident Date	23/03/2023	Inspection Date	28/03/2023	
Survey held at	31 CORPORATION ROAD SINGAPORE 649825			
Repairer	DING AUTOMOTIVE PTE LTD			
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	