



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23003210/Any3e2	
			Date: 16/05/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 5519C	Veh. Inspected	YQ 1642E
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2301224/THE	Excess (\$)	0.00
	Assign From	BETTY WONG	Assign Date	27/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	ISUZU NPR75	c.c	5193
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JAANPR75HK7100966	Colour	WHITE
	Odometer	16876 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/75 R17.5	WINDFORCE	6 mm
	L/H Front Tyre	215/75 R17.5	WINDFORCE	6 mm
	R/H Rear Tyre	215/75 R17.5	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/75 R17.5	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/03/2023	Inspection Date	29/03/2023
	Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	