

Estimate

DING AUTO PTE LTD

176, Sin Ming Dr, #04-06 Sin Ming AutoCare, Singapore, Singapore,
Singapore - 575721.

Contact: +65 9231 3123

Email: desmond@insurlogic.co

Proforma Invoice No:

Date: Mar 31 2023

Ticket No: DAP-J000007

Vehicle No: SJD5471B

Engine No: WBAWL72010JZ96424

Vehicle: BMW 3-SERIES 325I 2008

Kilometer: 105534

Color: WHITE

Fuel: PETROL

PH: +65 91140884, +65 91140884

Email: robert_i_cohen@outlook.com

Customer Name: Robert Ian Cohen

Mobile No: +65 91140884, +65 91140884

Not Notarized
11/19/02
Acknow After Posing
00884 6 days

#	Part Name	Description	Quantity	Unit Price	Taxable	Parts Total
1	FRONT BUMPER	Part	1.00	1,265.00	1,265.00	1,265.00
2	BONNET/HOOD ASSY	Part	1.00	1,375.00	1,375.00	1,375.00
3	HINGE, BONNET/HOOD (RH)	Part	1.00	71.50	71.50	71.50
4	HINGE, BONNET/HOOD (LH)	Part	1.00	71.50	71.50	71.50
5	RADIATOR ASSY	Part	1.00	902.00	902.00	902.00
6	BALL JOINT, STEERING (RH)	Part	1.00	242.00	242.00	242.00
7	ADLAMP ASSY LH	Part	1.00	2,860.00	2,860.00	2,860.00
8	FRONT SHOCK ABSORBER RH	Part	1.00	605.00	605.00	605.00
9	ARM, LOWER CONTROL (LOWER, RH)	Part	1.00	286.00	286.00	286.00
10	LINK, STABILIZER (RH)	Part	1.00	198.00	198.00	198.00
11	STABILIZER BAR (FR)	Part	1.00	506.00	506.00	506.00
12	SENSOR, WHEEL SPEED/ABS (FR, RH)	Part	1.00	280.50	280.50	280.50
13	END, TIE ROD (RH)	Part	1.00	264.00	264.00	264.00
14	WHEEL ALIGNMENT	Part	1.00	100.00	100.00	100.00
15	FRONT BUMPER TOW CAP	Part	1.00	55.00	55.00	55.00
16	BONNET BADGE	Part	1.00	82.50	82.50	82.50
17	FRONT LOWER GRILLE	Part	1.00	88.00	88.00	88.00
18	HEADLAMP ASSY RH	Part	1.00	2,860.00	2,860.00	2,860.00
19	HEADLAMP PANEL RH	Part	1.00	748.00	748.00	748.00
20	HEADLAMP BRACKET RH	Part	1.00	82.50	82.50	82.50
21	FOG LAMP ASSY RH	Part	1.00	385.00	385.00	385.00
22	FOG LAMP BRACKET RH	Part	1.00	110.00	110.00	110.00
23	FRONT FENDER RH	Part	1.00	935.00	935.00	935.00
24	CONDENSOR ASSY	Part	1.00	1,265.00	1,265.00	1,265.00
25	WASHER TANK	Part	1.00	132.00	132.00	132.00
26	WHEEL KNUCKLE RH	Part	1.00	572.00	572.00	572.00
27	WHEEL BEARING HUB	Part	1.00	583.00	583.00	583.00
28	BRAKE HOSE RH	Part	1.00	187.00	187.00	187.00
29	ENGINE LOWER COVER	Part	1.00	467.50	467.50	467.50
30	AIR DUCT RH	Part	1.00	236.50	236.50	236.50
31	FRONT BUMPER RETAINER RH	Part	1.00	66.00	66.00	66.00
32	FRONT BUMPER SIDE GARNISH RH	Part	1.00	88.00	88.00	88.00
33	FRONT BUMPER LOWER LIP GARNISH	Part	1.00	220.00	220.00	220.00
34	FRONT BUMPER LOWER GRILLE GARNISH	Part	1.00	93.50	93.50	93.50
35	FRONT BUMPER NUMBER PLATE REINF	Part	1.00	22.00	22.00	22.00
36	FRONT BUMPER NOZZLE COVER RH	Part	1.00	55.00	55.00	55.00
37	FRONT BUMPER NOZZLE JET RH	Part	1.00	181.50	181.50	181.50

#	Part Name	Description	Quantity	Unit Price	Taxable	Parts Total
38	BONNET LOCK RH	Part	1.00	137.50	137.50	137.50
39	BONNET LOCK LH	Part	1.00	137.50	137.50	137.50
40	BONNET LOCK BRACKET RH	Part	1.00	33.00	33.00	33.00
41	BONNET LOCK BRACKET LH	Part	1.00	33.00	33.00	33.00
42	FRONT AIR GRILLE RH	Part	1.00	198.00	198.00	198.00
43	FRONT AIR GRILLE LH	Part	1.00	198.00	198.00	198.00
44	FRONT SUPPORT PANEL CPL	Part	1.00	792.00	792.00	792.00
45	FRONT AIR VENT MOULDING CPL	Part	1.00	225.50	225.50	225.50
46	FRONT CROSS BRACE RH	Part	1.00	66.00	66.00	66.00
47	FRONT CROSS BRACE LH	Part	1.00	66.00	66.00	66.00
48	FRONT FENDER INNER SHIELD RH	Part	1.00	275.00	275.00	275.00
49	PARKING SENSOR RH	Part	1.00	275.00	275.00	275.00
50	RADIATOR AIR GUIDE RH	Part	1.00	93.50	93.50	93.50
51	RADIATOR AIR GUIDE LH	Part	1.00	93.50	93.50	93.50
52	INTERCOOLER - POWER STEERING	Part	1.00	924.00	924.00	924.00
53	WASHER TANK PUMP	Part	1.00	203.50	203.50	203.50
54	HORN - HIGH PITCH RH	Part	1.00	82.50	82.50	82.50
55	ABSORBER MOUNTING RH	Part	1.00	242.00	242.00	242.00
56	ABSORBER LINKAGE RH	Part	1.00	104.50	104.50	104.50
57	STEERING RACK CPL	Part	1.00	3,135.00	3,135.00	3,135.00
58	ENGINE LOWER SIDE COVER RH	Part	1.00	192.50	192.50	192.50
59	FRONT ALLOY RIM RH	Part	1.00	1,320.00	1,320.00	1,320.00
60	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	Part	1.00	1,200.00	1,200.00	1,200.00
61	REFILL - RADIATOR COOLANT	Part	1.00	100.00	100.00	100.00
62	REFILL - AIR COND GAS	Part	1.00	100.00	100.00	100.00
63	SPRAY PAINT - FRT BUMPER, FRT FENDER RH, FRT DOOR RH, BONNET & SUPPORT PANEL	Part	1.00	1,400.00	1,400.00	1,400.00
64	REMOVE & REFIT - UNDERCARRIAGE COMPONENTS	Part	1.00	350.00	350.00	350.00
65	ALIGN HEADLAMP/FOG LAMP/PARKING SENSOR & TEST WIRING	Part	1.00	150.00	150.00	150.00
66	HEADLAMP MODULE - DIAGNOSIS & RE-PROGRAMMING	Part	1.00	450.00	450.00	450.00
67	FRT GRILLE, FRT BUMPER, INNER SHIELD, GARNISH - CLIPS	Part	1.00	200.00	200.00	200.00
68	FRONT NUMBER PLATE & FRAME	Part	1.00	45.00	45.00	45.00

Taxable Value
 31,364.00
 Discount Total 0.00
 Grand Total
 31,364.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts Total	31,364.00
Labour Total	0.00
GST Total	0.00
Grand Total	31,364.00
Balance	31,364.00

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.