

CITYCAB PTE LTD
REPAIR ESTIMATE*

VEHICLE NO SHC 102D
MAKE REG. 01.08.2018
MODEL : HYUNDAI IONIQ G2

DATE 08.03.2023

CHIANG /CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET LH ?			\$55.80 xw
1	HEAD LAMP LH crn /			\$2,110.30 -
1	FRONT GRILLE CENTRE MOULDING ?			\$368.50 xw
1	FRONT BUMPER GRILLE LH scr /			\$186.90 -
1	FRONT DAY RUNNING LIGHT LH ?			\$642.50 xw
1	FRONT BUMPER crn /			\$481.10 -
1	FRONT FENDER EMBLEM LH NCC			\$26.60 -
1	FRONT FENDER SHIELD LH XNV			\$164.70
	SUB TOTAL		2804.90	\$4,036.40
	20.00%		560.98	\$807.28
	DISCOUNTED TOTAL			\$3,229.12
1	FRONT FENDER ADVERTISEMENT ncc			\$100.00 -
				\$100.00
	Labour Charge			
	Panel Beating			\$600.00 -
	Spray Painting			\$600.00 500
	Check Lighting			\$60.00 30
	TOTAL LABOUR			\$1,260.00
	ESTIMATE TOTAL		3473.92	\$4,589.12
	20% = 694.78			
	= 2779			
	2750			
	3 days			
	LIS			
	8/3/23			
	3pm			
	1hr			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: