

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SJZ6485P

NOT Authorized
L1 Reg &
Resurvey After Painting
8 days

No.	Qty	List Items
1	1	Front bumper
2	1	Front bumper RH fog lamp cover
3	1	Front bumper RH fog lamp
4	1	Front bumper RH parking sensor
5	1	Front bumper RH side retainer
6	1	Front bumper inner foam
7	1	Front bumper inner reinforcement
8	1	RH headlamp (HID)
9	1 set	Front fender under shield clips
10	1	Front RH sports rims
11	1	Front RH shock absorber
12	1	Front RH lower arm
13	1	Front RH trailing arm
14	1	Front RH wheel hub & bearing
15	1	Front RH knuckle arm

Bu/la	1,818.00	✓
\$	93.00	✓
\$	619.00	✓
\$	331.00	✓
\$	91.00	X
\$	148.00	✓
\$	700.00	X
\$	3,898.00	✓
\$	40.00	X
\$	1,330.00	✓
\$	1,067.00	X
\$	738.00	X
\$	728.00	X
\$	895.00	✓
\$	1,531.00	X
\$	14,027.00	
Less 10%	\$ 1,402.70	
Total :	\$ 12,624.30	

Special Nett Items

16	1	Front RH tyre
----	---	---------------

\$ 280.00X

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.
2	To putty and spray Spray Paintings charges.
3	To remove, refit front RH under carriages.
4	To conduct computerise wheel alignment test.
5	To check wirings and lightings.
6	To supplied and applied rust proofing treatments.

\$	600.00	30d
\$	800.00	44d
\$	250.00	7
\$	80.00	6d
\$	40.00	2d
\$	60.00	X
Total :	\$ 1,830.00	

Total Parts and Labour : \$ 14,734.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: