

08/11/13 Wef

SS.REC. BY: AM

REF:

962m 676m

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMC 63506

at Workshop m/s PREMIUM

of ALEXANDRA RD

Insured: AK

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 151K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days Res.: Yes or No

Lum Sum: _____

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMC 63506 Yr Regn: 2018 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi Q5 SP 2.0TFSI Quattro c.c. 1984

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 46341 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMA 222F49J2129114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____

Rear: _____

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 15/03/23

D.O.I. 28/03/23

Survey held at PREMIUM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LMA - 91K

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : S + RS (\$ _____)

☐ : Interview (\$ _____)

☐ : Photos

☐ : Tech. Invs (\$ _____)

☐ : Others

☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I. (\$ _____)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0311/2023/EQ
DATE : 27-Mar-23
WIP : 13870

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S PREMIUM LEASING PTE LTD
ADDRESS : 9 LENG KEE ROAD
SINGAPORE 159090

TELEPHONE : HP +65 85189509
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 0999993549-01
VEHICLE NO : **SMC 6350 E**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 13/7/2018
ENGINE NO : DAX 031529
CHASSIS NO : WAUZZZF9J2129114
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Mar-23
PLACE OF ACCIDENT : CAPELLA HOTEL AT SENTOSA

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 6350 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00 500	
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, REAR END PANELLING AND REAR BOTH WHEEL ARCH TRIMS. ? Change 1 = 400	\$ 3,500.00 1500	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 5,652.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 6350 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER - UPPER <i>de/</i>	1	\$	2,152.00	
2	REAR BUMPER - LOWER <i>de/</i>	1	\$	1,409.00	
3	REAR BUMPER SPOILER <i>de/</i>	1	\$	1,021.00	
4	REAR BUMPER TOW EYE COVER - LH <i>X</i>	1	\$	57.00	
5	REAR BUMPER TOW EYE COVER - RH <i>mis/</i>	1	\$	34.00	
6	REAR BUMPER CLOSING ELEMENT - RH <i>?</i>	1	\$	114.00	
7	REAR BUMPER CHROME TRIM - RH <i>X</i>	1	\$	281.00	
8	REAR BUMPER TAIL LIGHT - RH <i>can/</i>	1	\$	826.00	
9	REAR BOOT LID OPENING CONTROL UNIT <i>X</i>	1	\$	491.00	
10	REAR TAILGATE OPENING SENSOR LINE <i>X</i>	1	\$	129.00	
11	REAR AERIAL KEY ACCESS <i>X</i>	1	\$	123.00	
12	REAR BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$	1,104.00	
13	REAR BUMPER IMPACT BAR GASKET - LH / RH <i>?</i>	2	\$	7.00	
14	REAR BUMPER HOLDING STRAP <i>?</i>	1	\$	201.00	
15	REAR BUMPER GUIDE SECTION - LH / RH <i>X</i>	2	\$	200.00	
16	REAR PARKING AID SENSOR - INNER / OUTER <i>X</i>	2	\$	543.00	
17	REAR PARKING AID SEAL RING <i>see/</i>	4	\$	11.00	
18	REAR BUMPER WIRING SET <i>?</i>	1	\$	551.00	
19	REAR WHEEL COVER - LH / RH <i>see/</i>	2	\$	1,306.00	
20	SUNDRIES <i>?</i>		\$	400.00	
TOTAL SPARE PARTS		:	\$	10,960.00	
TOTAL LABOUR CHARGES		:	\$	5,652.00	
GRAND TOTAL		:	\$	16,612.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Rasu - H790020068
: 28/03/23 @ 1130
: 3 days
: EXCESS: TBA
: REVERT
: Resurvey before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	676M
Vehicle No.:	SMC6350E
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Mar 2023
Vehicle Make:	AUDI
Vehicle Model:	Q5 SPORT 2.0 TFSI QU S TRONIC
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	DAX031529
Chassis No.:	WAUZZZF9J2129114
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$44,970.00
Original Registration Date:	13 Jul 2018
First Registration Date:	13 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$54,958.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jul 2028
PARF Rebate Amount:	\$41,218.00
COE Expiry Date:	12 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,900.00
COE Rebate Amount:	\$17,916.00
Total Rebate Amount:	\$59,134.00

The information contained herein is correct as at 29 Mar 2023

OK

Audi Q5 2.0A TFSI Quattro S-tronic Sport

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)**Price****\$159,000****Depreciation** ?

\$23,490 /yr

[View models with similar depre](#)**Reg Date**

22-Nov-2018

(5yrs 7mths 23days COE left)

Mileage

30,000 km (6.9k /yr)

Manufactured ?

2018

Road Tax ?

\$1,194 /yr

Transmission

Auto

Dereg Value ?

\$57,484 as of today (change)

OMV ?

\$43,064

COE ?

\$32,302

ARF ?

\$52,290

Engine Cap

1,984 cc

Power

185.0 kW (248 bhp)

Curb Weight ?

1,795 kg

No. of Owners ?

1

Type of Vehicle

SUV