

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LIBERTY INSURAI	NCE PTE LTD		Ref:	CS3/LIP23003265/Kqy3
	51 CLUB STREET	, #03-00 SINGAPORE 069428		Date:	29/03/2023
				Code:	LIP
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKR 779L	Veh. Inspected		SMR 957R
	Policy No.		Coverage (\$)		0.00
	Claim No.	IVS23/0612	Excess (\$)		0.00
	Assign From	ANDY SEAH	Assign Date		29/03/2023
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes	Modification			
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4. Description of Damages					
5.	General Information				
	Accident Date	20/03/2023	Inspection Date	е	29/03/2023
	Survey held at	CELEBRITY AUTO			
		BLK 176 SIN MING DRIVE #03-18 SIN MING AUTOCARE SINGAPORE 575721			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				