



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref: CS3/AIG23003277/Rqy3

78 SHENTON WAY #09-16

Date: 29/03/2023

AIG BUILDING

SINGAPORE 079120

Code: AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLN 9633Z	Veh. Inspected	FBT 2417P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	VILASINI PERUMAL	Assign Date	29/03/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/03/2023	Inspection Date	29/03/2023
Survey held at	SPEEDWAY MOTOR PL 36 TOH GUAN ROAD EAST #01-32 ENTERPRISE HUB SINGAPORE 608580		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--