



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC23002343/Tny3e2-1 Date: 11/04/2023 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SFU 49D	Veh. Inspected	SCP 32M
	Policy No.		Coverage (\$)	0.00
	Claim No.	23/23/23/VP05/027065	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	29/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA LEXUS ES250	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTHBJ1GG702090801	Colour	GREY
	Odometer	139612 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	255/35 R19	BRIDGESTONE	6 mm
	L/H Front Tyre	255/35 R19	BRIDGESTONE	6 mm
	R/H Rear Tyre	255/35 R19	BRIDGESTONE	6 mm
	L/H Rear Tyre	255/35 R19	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	03/03/2023	Inspection Date	06/03/2023
	Survey held at	INFINITY CAPITAL & INSURANCE 38 WOODLAND CLOSE #01-08 MEGA @ WOODLAND SINGAPORE 737856		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	