

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 20 Apr 2023

Preliminary Advice

| | | | |
|--------------------|---------------------------------|-------------------------|----------------|
| Vehicle No | : SMQ4584L | Accident Date | : 29/03/2023 |
| Make | : HYUNDAI AVANTE | Policy No. | : SP2004848774 |
| Assignment Date | : 29/03/2023 | Excess | : S\$600.00 |
| Date of Inspection | : 30/03/2023 | Est. Duration of Repair | : 5 days |
| Inspection At | : SHU FATT AUTO WORKS (Desktop) | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 7,010.90 |
| Revised Amount | :S\$ | 4,717.30 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 4,717.30 |
| Lump Sum Repair | :S\$ | 3,300.00 |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 13,000.00 |
| COE / PARF Rebate | :S\$ | 5,552.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 7,448.00 |

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Kindly approve on Final Cost of Repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.