



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC23003347/Sqy3e2

Date: 18/07/2023

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKT 7673B	<b>Veh. Inspected</b>	SLR 3345Z
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1215590-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JURAIDAH ABBAS	<b>Assign Date</b>	30/03/2023

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI ELANTRA	<b>c.c</b>	1591
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	KMHD841CMJU526456	<b>Colour</b>	GREY
<b>Odometer</b>	75036 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/45 R17	GOODYEAR	6 mm
<b>L/H Front Tyre</b>	215/45 R17	GOODYEAR	6 mm
<b>R/H Rear Tyre</b>	215/45 R17	GOODYEAR	6 mm
<b>L/H Rear Tyre</b>	215/45 R17	GOODYEAR	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

<b>Accident Date</b>	23/03/2023	<b>Inspect Date / Time</b>	30/03/2023 ( 04:30 PM )
<b>Survey held at</b>	AP AUTOMOTIVE SERVICES PTE LTD 9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**